Register entry, as of 29 October 2026 Listed for sale Record ID a29f6708d1a8

2023 Mercedes-Benz EQS-Class SUV EQS580 4MATIC

0.0 L · AWD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

4JG	DM4EB	1	P	A	011919
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Of North A…	EQS-Class SUV · 0.0 L	Verified	2023	United States	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	0.0 L
Make	Mercedes-Benz	Fuel	Electric
Model	EQS-Class SUV	Drive	AWD
Trim	EQS580 4MATIC	Maker	MERCEDES-BENZ OF NORTH AMERICA, INC.
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/eqs-class-suv/2023

4 recalls listed by Transport Canada for this model year

Other

2025298 30 May 2025

Issue: On a small number of vehicles, a software problem could cause the vehicle alerting system not to work properly. As a result, the vehicle may make the wrong sound when reversing. Safety Risk: A vehicle alerting system that doesn't work properly could create an increased risk of a crash and/or injury. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the acoustic vehicle alerting system software.

Electrical

2025213 17 Apr 2025

Issue: On certain vehicles, the recall repairs completed by a Mercedes-Benz dealer during recall 8297011 (Transport Canada recall no. 2024-105) may not have been done correctly. As a result, a second repair is required. On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

High voltage

2024296 24 May 2024

Issue: On certain vehicles, a software problem could cause the main contactors for the high-voltage battery to open. If this happens, there could be a sudden loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the battery management system software.

Electrical

2024105 16 Feb 2024

Issue: On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $69,900[4], $95 under the median of $69,995[3].

Lowest ask	$55,990
Middle half	$62,877 – $73,900
Median ask	$69,995
This car	$69,900

Same model year · 9 live listings · as of 29 Oct 2026

OTHER 2023 MERCEDES-BENZ EQS-CLASS SUV LISTINGS [4]

Mirabel, QC · 114,421 km	$26,890
Milton, ON · 15,100 km	$53,125
Mirabel, QC · 38,693 km	$34,844
Laval, QC · 33,100 km	$37,995
Edmonton, AB · 26,058 km	$59,995
Edmonton, AB · 58,719 km	$44,184

§4 EVENTS

2023	Model year 2023[1] Assembly plant United States
16 Feb 2024	Transport Canada recall 2024105[2] Issued for the model year · Electrical
24 May 2024	Transport Canada recall 2024296[2] Issued for the model year · High voltage

17 Apr 2025	Transport Canada recall 2025213[2] Issued for the model year · Electrical
30 May 2025	Transport Canada recall 2025298[2] Issued for the model year · Other
27 Oct 2026	Listed for sale, North Vancouver, BC[4] Park Shore BMW · asking $69,900
29 Oct 2026	Listing last updated[4] asking $69,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 9 live listings, as of 29 Oct 2026
[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.