Register entry, as of 27 October 2026 Listed for sale Record ID e47327c7e98e

# 2023 Mercedes-Benz EQS-Class SUV EQS580 4MATIC

0.0 L · AWD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

| 4JG | DM4EB | 8 | P | A | 001968 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mercedes-Benz Of North A… | EQS-Class SUV · 0.0 L | Verified | 2023 | United States | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 0.0 L |
| Make | Mercedes-Benz | Fuel | Electric |
| Model | EQS-Class SUV | Drive | AWD |
| Trim | EQS580 4MATIC | Maker | MERCEDES-BENZ OF NORTH AMERICA, INC. |
| Body | Sport Utility Vehicle | Plant | United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/eqs-class-suv/2023

**4** recalls listed by Transport Canada for this model year

### Other

2025298 30 May 2025

Issue: On a small number of vehicles, a software problem could cause the vehicle alerting system not to work properly. As a result, the vehicle may make the wrong sound when reversing. Safety Risk: A vehicle alerting system that doesn't work properly could create an increased risk of a crash and/or injury. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the acoustic vehicle alerting system software.

### Electrical

2025213 17 Apr 2025

Issue: On certain vehicles, the recall repairs completed by a Mercedes-Benz dealer during recall 8297011 (Transport Canada recall no. 2024-105) may not have been done correctly. As a result, a second repair is required. On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

### High voltage

2024296 24 May 2024

Issue: On certain vehicles, a software problem could cause the main contactors for the high-voltage battery to open. If this happens, there could be a sudden loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the battery management system software.

### Electrical

2024105 16 Feb 2024

Issue: On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

## §3 VALUE [3]

This car asks $73,877[4], $1,977 over the median of $71,900[3].

| | |
|---|---|
| Lowest ask | $55,990 |
| Middle half | $67,436 – $74,398 |
| Median ask | $71,900 |
| This car | $73,877 |

Same model year · 7 live listings · as of 27 Oct 2026

### OTHER 2023 MERCEDES-BENZ EQS-CLASS SUV LISTINGS [4]

| | |
|---|---|
| Calgary, AB · 22,024 km | $55,990 |
| Mirabel, QC · 88,990 km | $59,895 |
| Mirabel, QC · 55,203 km | $54,888 |
| Mirabel, QC · 40,124 km | $62,895 |
| Toronto, ON · 26,597 km | $67,777 |
| Halifax, NS · 119,562 km | $65,990 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant United States |
| 16 Feb 2024 | Transport Canada recall 2024105[2]<br>Issued for the model year · Electrical |
| 24 May 2024 | Transport Canada recall 2024296[2]<br>Issued for the model year · High voltage |

| | |
|---|---|
| 17 Apr 2025 | Transport Canada recall 2025213[2]<br>Issued for the model year · Electrical |
| 30 May 2025 | Transport Canada recall 2025298[2]<br>Issued for the model year · Other |
| 26 Aug 2026 | Listed for sale, Mirabel, QC[4]<br>Mercedes-Benz de Blainville · asking $73,877 |
| 27 Oct 2026 | Listing last updated[4]<br>asking $73,877 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 7 live listings, as of 27 Oct 2026
[4] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.