

Register entry, as of 29 October 2026

Listed for sale

Record ID 7fd3245be41f

# 2021 Mercedes-Benz GLE-Class GLE450-4M

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4JG

WMI 1-3

Mercedes-Benz Of North A...

FB5KE

DESCRIPTOR 4-8

GLE-Class · 3.0 L

8

CHECK 9

Verified

M

YEAR 10

2021

A

PLANT 11

United States

538399

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                      |
|------------|-----------------------|--------|--------------------------------------|
| Model year | 2021                  | Engine | 3.0 L, 6 cylinders                   |
| Make       | Mercedes-Benz         | Fuel   | Gasoline                             |
| Model      | GLE-Class             | Drive  | Not in the decode                    |
| Trim       | GLE450-4M             | Maker  | MERCEDES-BENZ OF NORTH AMERICA, INC. |
| Body       | Sport Utility Vehicle | Plant  | United States                        |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/mercedes-benz/gle-class/2021](https://cardog.app/tools/recalls/mercedes-benz/gle-class/2021)

## 18 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |         |             |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| <b>Airbag</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | 2024567 | 27 Sep 2024 |
| Issue: On certain vehicles, the wiring harness for an acceleration sensor may not have been routed properly. As a result, the wiring could become damaged in a crash and cause the driver- and passenger-front airbags to deploy with too much force. Safety Risk: An airbag that inflates with too much force could create an increased risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, re-route the wiring harness. |         |             |
| <b>Electrical</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 2024171 | 15 Mar 2024 |
| Issue: On certain vehicles, the bolt for the 48 V ground connection under the passenger seat may not have been tightened properly. As a result, the wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the ground connection.                                                                                                   |         |             |
| <b>Powertrain</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | 2024103 | 16 Feb 2024 |
| Issue: Under certain conditions, a software problem could cause the engine to stall during a downshift. As a result, there could be a sudden loss of power to the wheels. Note: This recall only affects vehicles equipped with a V6 engine and a 9-speed automatic transmission. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control unit software.      |         |             |



**Fuel system**

2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

**Electrical**

2023651 8 Dec 2023

Issue: On certain vehicles, the bolt for the 12V ground connection under the driver seat may not have been properly tightened. As a result, the connection could loosen and overheat. Safety Risk: A loose or overheated ground connection could create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the 12V ground connection.

**Fuel system**

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

12 more on the model-year record, [cardog.app/tools/recalls/mercedes-benz/gle-class/2021](https://cardog.app/tools/recalls/mercedes-benz/gle-class/2021)

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.

Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

[www.mercedes-benz.ca/en/recalls](https://www.mercedes-benz.ca/en/recalls)

**§3 VALUE [3]**

This car asks \$47,980<sup>[4]</sup>, \$15 under the median of \$47,995<sup>[3]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$36,995            |
| Middle half | \$44,985 – \$57,777 |
| Median ask  | \$47,995            |
| This car    | \$47,980            |

Same model year · 45 live listings · as of 29 Oct 2026

**OTHER 2021 MERCEDES-BENZ GLE-CLASS LISTINGS [4]**

|                              |          |
|------------------------------|----------|
| Mississauga, ON · 118,005 km | \$55,950 |
| Mississauga, ON · 88,788 km  | \$44,999 |
| Mississauga, ON · 78,031 km  | \$57,777 |
| Burnaby, BC · 109,200 km     | \$42,995 |
| Surrey, BC · 58,500 km       | \$45,986 |
| Concord, ON · 93,120 km      | \$46,888 |

**§4 EVENTS**

2021 Model year 2021<sup>[1]</sup>  
Assembly plant United States



|             |                                                                                                      |
|-------------|------------------------------------------------------------------------------------------------------|
| 3 Nov 2020  | Transport Canada recall 2020522 <sup>[2]</sup><br>Issued for the model year · Seats and restraints   |
| 1 Feb 2021  | Transport Canada recall 2021041 <sup>[2]</sup><br>Issued for the model year · Accessories            |
| 12 Feb 2021 | Transport Canada recall 2021064 <sup>[2]</sup><br>Issued for the model year · Electrical             |
| 14 May 2021 | Transport Canada recall 2021291 <sup>[2]</sup><br>Issued for the model year · Visual system          |
| 5 Jul 2021  | Transport Canada recall 2021415 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 8 Apr 2022  | Transport Canada recall 2022173 <sup>[2]</sup><br>Issued for the model year · Electrical             |
| 12 Apr 2022 | Transport Canada recall 2022177 <sup>[2]</sup><br>Issued for the model year · Visual system          |
| 20 May 2022 | Transport Canada recall 2022263 <sup>[2]</sup><br>Issued for the model year · Other                  |
| 6 Jul 2022  | Transport Canada recall 2022359 <sup>[2]</sup><br>Issued for the model year · Label                  |
| 9 Sep 2022  | Transport Canada recall 2022509 <sup>[2]</sup><br>Issued for the model year · Structure              |
| 16 Dec 2022 | Transport Canada recall 2022724 <sup>[2]</sup><br>Issued for the model year · Steering               |
| 17 Mar 2023 | Transport Canada recall 2023150 <sup>[2]</sup><br>Issued for the model year · Heater and defroster   |
| 23 Jun 2023 | Transport Canada recall 2023353 <sup>[2]</sup><br>Issued for the model year · Fuel system            |
| 8 Dec 2023  | Transport Canada recall 2023651 <sup>[2]</sup><br>Issued for the model year · Electrical             |
| 15 Dec 2023 | Transport Canada recall 2023672 <sup>[2]</sup><br>Issued for the model year · Fuel system            |
| 16 Feb 2024 | Transport Canada recall 2024103 <sup>[2]</sup><br>Issued for the model year · Powertrain             |
| 15 Mar 2024 | Transport Canada recall 2024171 <sup>[2]</sup><br>Issued for the model year · Electrical             |
| 27 Sep 2024 | Transport Canada recall 2024567 <sup>[2]</sup><br>Issued for the model year · Airbag                 |
| 6 Oct 2026  | Listed for sale, Toronto, ON <sup>[4]</sup><br>KMS Fine Cars · asking \$47,980                       |



28 Oct 2026      Listing last updated<sup>[4]</sup>  
asking \$47,980

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                 |                                                                               |
|-----------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN              | [3] Cardog market quote, same model year, 45 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 29 Oct 2026                  |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

