

Register entry, as of 29 October 2026

Listed for sale

Record ID 5dc54d22f21d

# 2023 Mercedes-Benz GLE-Class AMG GLE53 4MATIC+

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**4JG** **FB6BB** **1** **P** **A** **927126**

WMI 1-3

Mercedes-Benz Of North A...

DESCRIPTOR 4-8

GLE-Class · 3.0 L

CHECK 9

Verified

YEAR 10

2023

PLANT 11

United States

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                      |
|------------|-----------------------|--------|--------------------------------------|
| Model year | 2023                  | Engine | 3.0 L, 6 cylinders                   |
| Make       | Mercedes-Benz         | Fuel   | Gasoline                             |
| Model      | GLE-Class             | Drive  | AWD                                  |
| Trim       | AMG GLE53 4MATIC+     | Maker  | MERCEDES-BENZ OF NORTH AMERICA, INC. |
| Body       | Sport Utility Vehicle | Plant  | United States                        |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/mercedes-benz/gle-class/2023](https://cardog.app/tools/recalls/mercedes-benz/gle-class/2023)

## 5 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |         |             |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| Electrical                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 2024171 | 15 Mar 2024 |
| Issue: On certain vehicles, the bolt for the 48 V ground connection under the passenger seat may not have been tightened properly. As a result, the wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the ground connection.                                                                                              |         |             |
| Powertrain                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 2024103 | 16 Feb 2024 |
| Issue: Under certain conditions, a software problem could cause the engine to stall during a downshift. As a result, there could be a sudden loss of power to the wheels. Note: This recall only affects vehicles equipped with a V6 engine and a 9-speed automatic transmission. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control unit software. |         |             |
| Fuel system                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | 2023672 | 15 Dec 2023 |
| Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.                                   |         |             |



**Fuel system**

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

**Structure**

2023151 17 Mar 2023

Issue: On certain vehicles, the window trim on the rear doors may not be properly attached. As a result, the window trim could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada Recall 2022-509 Safety Risk: Window trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the window trim on the rear doors and repair them, if necessary.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.

Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

[www.mercedes-benz.ca/en/recalls](http://www.mercedes-benz.ca/en/recalls)

**§3 VALUE [3]**

This car asks \$73,900<sup>[4]</sup>, \$8,314 over the median of \$65,586<sup>[3]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$47,988            |
| Middle half | \$57,142 – \$74,968 |
| Median ask  | \$65,586            |
| This car    | \$73,900            |

Same model year · 54 live listings · as of 29 Oct 2026

**OTHER 2023 MERCEDES-BENZ GLE-CLASS LISTINGS [4]**

|                          |           |
|--------------------------|-----------|
| Regina, SK · 96,506 km   | \$66,285  |
| Richmond, BC · 34,288 km | \$125,995 |
| Toronto, ON · 72,000 km  | \$72,800  |
| Burnaby, BC · 30,741 km  | \$74,888  |
| Markham, ON · 39,900 km  | \$55,995  |

**§4 EVENTS**

2023

Model year 2023<sup>[1]</sup>

Assembly plant United States

17 Mar 2023

Transport Canada recall 2023151<sup>[2]</sup>

Issued for the model year · Structure

23 Jun 2023

Transport Canada recall 2023353<sup>[2]</sup>

Issued for the model year · Fuel system

15 Dec 2023

Transport Canada recall 2023672<sup>[2]</sup>

Issued for the model year · Fuel system



|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 16 Feb 2024 | Transport Canada recall 2024103 <sup>[2]</sup><br>Issued for the model year · Powertrain |
| 15 Mar 2024 | Transport Canada recall 2024171 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 14 Oct 2026 | Listed for sale, Vaughan, ON <sup>[4]</sup><br>Toronto Auto Brokers · asking \$73,900    |
| 29 Oct 2026 | Listing last updated <sup>[4]</sup><br>asking \$73,900                                   |

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                 |                                                                               |
|-----------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN              | [3] Cardog market quote, same model year, 54 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 29 Oct 2026                  |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

