Register entry, as of 27 October 2026 Listed for sale Record ID ae1e76477ec4

2021 Mercedes-Benz GLS-Class GLS450-4M

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4JG	FF5KE	2	M	A	351812
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Of North A…	GLS-Class · 3.0 L	Verified	2021	United States	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GLS-Class	Drive	Not in the decode
Trim	GLS450-4M	Maker	MERCEDES-BENZ OF NORTH AMERICA, INC.
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/gls-class/2021

14 recalls listed by Transport Canada for this model year

Electrical

2024171 15 Mar 2024

Issue: On certain vehicles, the bolt for the 48 V ground connection under the passenger seat may not have been tightened properly. As a result, the wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the ground connection.

Powertrain

2024103 16 Feb 2024

Issue: Under certain conditions, a software problem could cause the engine to stall during a downshift. As a result, there could be a sudden loss of power to the wheels. Note: This recall only affects vehicles equipped with a V6 engine and a 9-speed automatic transmission. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control unit software.

Fuel system

2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Heater and defroster

2023150 17 Mar 2023

Issue: On certain vehicles, the air conditioning drain hose might be installed incorrectly. This could allow water to leak inside the vehicle. If this happens, electrical components could short circuit. This could affect different parts, such as the door locks and emergency call (eCall) system. It could also result in reduced engine power or cause the vehicle not to start. Note: If this issue is present in your vehicle, you might notice wet carpets in the driver or passenger footwell and fogged windows. This is an expansion of Transport Canada Recall 2021-247. Safety Risk: A loss of engine power could increase the risk of a crash. If the doors cannot be unlocked in an emergency situation, it may be difficult to exit the vehicle. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect how the air conditioning hose is installed and correct it, if necessary. Mercedes-Benz recommends that you should not use the air conditioning until the vehicle is inspected.

Seats and restraints

2022551 29 Sep 2022

Issue: On certain vehicles, the springs that lock the backrest for the third-row seat may not have been installed correctly. As a result, the seat backrest may not fully lock in place. Safety Risk: A seat backrest that isn't locked could move in a crash and increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the third-row seat, and replace the backrest if necessary. To reduce the safety risk, Mercedes-Benz recommends that you should not transport any passengers in the third-row seat until the recall repairs have been completed.

8 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/gls-class/2021

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $45,888[4], $9,560 under the median of $55,448[3].



Lowest ask	$45,888
Middle half	$50,491 – $62,995
Median ask	$55,448
This car	$45,888

Same configuration · 10 live listings · as of 27 Oct 2026

OTHER 2021 MERCEDES-BENZ GLS-CLASS LISTINGS [4]

Brampton, ON · 131,895 km	$86,995
Concord, ON · 93,128 km	$48,888
Burlington, ON · 79,796 km	$64,350
Richmond, BC · 50,722 km	$62,995

§4 EVENTS

2021 Model year 2021[1]
Assembly plant United States

3 Nov 2020	Transport Canada recall 2020522[2] Issued for the model year · Seats and restraints
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
14 May 2021	Transport Canada recall 2021291[2] Issued for the model year · Visual system
8 Apr 2022	Transport Canada recall 2022173[2] Issued for the model year · Electrical
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other
6 Jul 2022	Transport Canada recall 2022359[2] Issued for the model year · Label
9 Sep 2022	Transport Canada recall 2022509[2] Issued for the model year · Structure
29 Sep 2022	Transport Canada recall 2022551[2] Issued for the model year · Seats and restraints
17 Mar 2023	Transport Canada recall 2023150[2] Issued for the model year · Heater and defroster
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
15 Dec 2023	Transport Canada recall 2023672[2] Issued for the model year · Fuel system
16 Feb 2024	Transport Canada recall 2024103[2] Issued for the model year · Powertrain
15 Mar 2024	Transport Canada recall 2024171[2] Issued for the model year · Electrical
20 Jul 2026	Listed for sale, Burnaby, BC[4] BC Auto Centre · asking $45,888
24 Oct 2026	Listing last updated[4] asking $45,888

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same configuration, 10 live listings, as of 27 Oct 2026

[4] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.