

Register entry, as of 29 October 2026

Listed for sale

Record ID 66c4134a14e7

# 2022 Mercedes-Benz GLS-Class GLS450 4MATIC

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**4JG FF5KE 5 N A 729011**

WMI 1-3

Mercedes-Benz Of North A...

DESCRIPTOR 4-8

GLS-Class · 3.0 L

CHECK 9

Verified

YEAR 10

2022

PLANT 11

Kecskemet

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                      |
|------------|-----------------------|--------|--------------------------------------|
| Model year | 2022                  | Engine | 3.0 L, 6 cylinders                   |
| Make       | Mercedes-Benz         | Fuel   | Gasoline                             |
| Model      | GLS-Class             | Drive  | AWD                                  |
| Trim       | GLS450 4MATIC         | Maker  | MERCEDES-BENZ OF NORTH AMERICA, INC. |
| Body       | Sport Utility Vehicle | Plant  | Kecskemet, Hungary                   |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/mercedes-benz/gls-class/2022](https://cardog.app/tools/recalls/mercedes-benz/gls-class/2022)

## 9 recalls listed by Transport Canada for this model year

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |         |             |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-------------|
| Electrical                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 2024171 | 15 Mar 2024 |
| Issue: On certain vehicles, the bolt for the 48 V ground connection under the passenger seat may not have been tightened properly. As a result, the wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the ground connection.                                                                                              |         |             |
| Powertrain                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 | 2024103 | 16 Feb 2024 |
| Issue: Under certain conditions, a software problem could cause the engine to stall during a downshift. As a result, there could be a sudden loss of power to the wheels. Note: This recall only affects vehicles equipped with a V6 engine and a 9-speed automatic transmission. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control unit software. |         |             |
| Fuel system                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | 2023672 | 15 Dec 2023 |
| Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.                                   |         |             |



**Fuel system**

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

**Structure**

2023151 17 Mar 2023

Issue: On certain vehicles, the window trim on the rear doors may not be properly attached. As a result, the window trim could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada Recall 2022-509 Safety Risk: Window trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the window trim on the rear doors and repair them, if necessary.

**Seats and restraints**

2022551 29 Sep 2022

Issue: On certain vehicles, the springs that lock the backrest for the third-row seat may not have been installed correctly. As a result, the seat backrest may not fully lock in place. Safety Risk: A seat backrest that isn't locked could move in a crash and increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the third-row seat, and replace the backrest if necessary. To reduce the safety risk, Mercedes-Benz recommends that you should not transport any passengers in the third-row seat until the recall repairs have been completed.

3 more on the model-year record, [cardog.app/tools/recalls/mercedes-benz/gls-class/2022](https://cardog.app/tools/recalls/mercedes-benz/gls-class/2022)

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.  
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.  
[www.mercedes-benz.ca/en/recalls](https://www.mercedes-benz.ca/en/recalls)

**§3 VALUE [3]**

This car asks \$65,888<sup>[4]</sup>, \$2,107 under the median of \$67,995<sup>[3]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$58,888            |
| Middle half | \$60,777 – \$69,995 |
| Median ask  | \$67,995            |
| This car    | \$65,888            |

Same configuration · 9 live listings · as of 29 Oct 2026

**OTHER 2022 MERCEDES-BENZ GLS-CLASS LISTINGS [4]**

|                            |          |
|----------------------------|----------|
| Chilliwack, BC · 71,500 km | \$67,995 |
| Regina, SK · 96,788 km     | \$77,987 |
| Richmond, BC · 44,290 km   | \$69,995 |
| Abbotsford, BC · 49,000 km | \$78,888 |

**§4 EVENTS**

|            |                                                                                          |
|------------|------------------------------------------------------------------------------------------|
| 2022       | Model year 2022 <sup>[1]</sup><br>Assembly plant Kecskemet, Hungary                      |
| 8 Apr 2022 | Transport Canada recall 2022173 <sup>[2]</sup><br>Issued for the model year · Electrical |



|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 20 May 2022 | Transport Canada recall 2022263 <sup>[2]</sup><br>Issued for the model year · Other                |
| 9 Sep 2022  | Transport Canada recall 2022509 <sup>[2]</sup><br>Issued for the model year · Structure            |
| 29 Sep 2022 | Transport Canada recall 2022551 <sup>[2]</sup><br>Issued for the model year · Seats and restraints |
| 17 Mar 2023 | Transport Canada recall 2023151 <sup>[2]</sup><br>Issued for the model year · Structure            |
| 23 Jun 2023 | Transport Canada recall 2023353 <sup>[2]</sup><br>Issued for the model year · Fuel system          |
| 15 Dec 2023 | Transport Canada recall 2023672 <sup>[2]</sup><br>Issued for the model year · Fuel system          |
| 16 Feb 2024 | Transport Canada recall 2024103 <sup>[2]</sup><br>Issued for the model year · Powertrain           |
| 15 Mar 2024 | Transport Canada recall 2024171 <sup>[2]</sup><br>Issued for the model year · Electrical           |
| 23 Sep 2026 | Listed for sale, North Vancouver, BC <sup>[4]</sup><br>Pacific Honda · asking \$65,888             |
| 28 Oct 2026 | Listing last updated <sup>[4]</sup><br>asking \$65,888                                             |

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                 |                                                                                 |
|-----------------------------------------------------------------|---------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN              | [3] Cardog market quote, same configuration, 9 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 29 Oct 2026                    |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

