Register entry, as of 28 October 2026 Listed for sale Record ID f59e3e223628

2020 Subaru Impreza

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4S3	GKAG6	8	L	3	601653
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Of America, Inc	Impreza · 2.0 L	Verified	2020	United States	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Impreza	Drive	Not in the decode
Trim	Not in the decode	Maker	SUBARU OF AMERICA, INC
Body	Sedan	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/impreza/2020

3 recalls listed by Transport Canada for this model year

Lights and instruments

2022394 21 Jul 2022

Issue: Over time, the backup lamp switch could corrode and fail. If this happens, the backup lamps will not turn on when the transmission is shifted into reverse and the shift position will not display. Additionally, for vehicles equipped with a rearview camera, the camera image will not appear on the display in the instrument cluster. Safety Risk: Backup lamps that do not work properly could cause a person not to recognize that the vehicle is backing. A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. These issues could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to inspect, and if necessary, replace the backup lamp switch.

Tires

2021209 7 Apr 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could cause a tire failure and lead to sudden loss of air pressure. Note: This recall only affects certain 16 inch Continental tires, with specific date codes and mould numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect all four tires. If one tire is affected, all four tires will be replaced.

Tires

2020521 2 Nov 2020

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could cause a tire failure and lead to sudden loss of air pressure. Note: This recall only affects vehicles equipped with certain Continental tires, with a date code of 2420 and mold number 416290. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to inspect all four tires. If one tire is affected, all four tires will be replaced

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $17,950[5], $1,511 over the median of $16,439[4].

Lowest ask	$12,695
Middle half	$15,621 – $18,137
Median ask	$16,439
This car	$17,950

Same model year · 24 live listings · as of 28 Oct 2026

OTHER 2020 SUBARU IMPREZA LISTINGS [5]

Saint-Georges, QC · 93,308 km	$15,998
Orleans, ON · 110,888 km	$18,882
Charlottetown, PE · 83,417 km	$16,995
Sherbrooke, QC · 145,000 km	$14,988
Thunder Bay, ON · 49,263 km	$22,999
Terrebonne, QC · 155,584 km	$13,499

§4 EVENTS

2020	Model year 2020[1] Assembly plant United States
2 Nov 2020	Transport Canada recall 2020521[2] Issued for the model year · Tires
7 Apr 2021	Transport Canada recall 2021209[2] Issued for the model year · Tires
21 Jul 2022	Transport Canada recall 2022394[2] Issued for the model year · Lights and instruments
26 Oct 2026	Listed for sale, Quebec, QC[5] autojeanvezina.com · asking $17,950
28 Oct 2026	Listing last updated[5] asking $17,950

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 24 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.