

Register entry, as of 27 October 2026

Listed for sale

Record ID cab1b9c2d27a

2019 Subaru Impreza Limited +NAVI +ES +BSD/N Limited +NAVI +ES +BSD

2.0 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4S3 **GTAU6** **0** **K** **3** **703478**

WMI 1-3

Subaru Of America, Inc

DESCRIPTOR 4-8

Impreza · 2.0 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

United States

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Impreza	Drive	Not in the decode
Trim	Limited +NAVI +ES +BSD/N Limited +NAVI +ES +BSD	Maker	SUBARU OF AMERICA, INC
Body	Hatchback	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/impreza/2019

7

 recalls listed by Transport Canada for this model year

Lights and instruments

2022538 23 Sep 2022

Issue: On certain vehicles, the side reflex reflectors in the headlamp assemblies may not reflect enough light at some viewing angles. Additionally, the low beam reflector in the left headlamp may not reflect light correctly. As a result, the reflectors may not meet the requirements of Canadian regulations. Note: This recall only affects vehicles equipped with halogen headlamps. Safety Risk: Reflex reflectors that do not reflect enough light may make the vehicle less visible to other road users. A low beam that is not reflected correctly could cause glare for oncoming drivers. Both issues could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail. The corrective actions for this recall are under development.

Lights and instruments

2022394 21 Jul 2022

Issue: Over time, the backup lamp switch could corrode and fail. If this happens, the backup lamps will not turn on when the transmission is shifted into reverse and the shift position will not display. Additionally, for vehicles equipped with a rearview camera, the camera image will not appear on the display in the instrument cluster. Safety Risk: Backup lamps that do not work properly could cause a person not to recognize that the vehicle is backing. A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. These issues could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to inspect, and if necessary, replace the backup lamp switch.



Fuel system

2021466 29 Jul 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Electrical

2021228 15 Apr 2021

Issue: On certain vehicles, the engine control module (ECM) may have been programmed incorrectly. As a result, the internal temperature of the ignition coils may increase. This could cause a short circuit and a blown fuse. This may result in a sudden loss of engine power with an inability to immediately restart. Note: This recall replaces WUQ-02 (Transport Canada recall 2019-526). Vehicles that were repaired under that recall also require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to reprogram the ECM if necessary, and replace the ignition coils. On vehicles with ignition coil damage, if a certain trouble code (DTC) is stored, the front exhaust pipe will also be replaced.

Tires

2021209 7 Apr 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could cause a tire failure and lead to sudden loss of air pressure. Note: This recall only affects certain 16 inch Continental tires, with specific date codes and mould numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect all four tires. If one tire is affected, all four tires will be replaced.

Fuel system

2020162 16 Apr 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.


1 more on the model-year record, cardog.app/tools/recalls/subaru/impreza/2019

Listed for the model year, not checked against your VIN. Subaru confirms which apply.
Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$23,110^[5], \$7,312 over the median of \$15,798^[4].



Lowest ask	\$8,899
Middle half	\$14,020 – \$17,188
Median ask	\$15,798
This car	\$23,110

Same model year · 27 live listings · as of 27 Oct 2026

OTHER 2019 SUBARU IMPREZA LISTINGS ^[5]

Québec, QC · 143,379 km	\$14,389
Waterloo, ON · 106,000 km	\$17,995
Thunder Bay, ON · 91,203 km	\$19,999
Laval, QC · 173,000 km	\$8,899
Acton Vale, QC · 102,538 km	\$16,495
Saint-hyacinthe, QC · 135,245 km	\$14,042



§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant United States
17 Oct 2019	Transport Canada recall 2019526 ^[2] Issued for the model year · Engine
16 Apr 2020	Transport Canada recall 2020162 ^[2] Issued for the model year · Fuel system
7 Apr 2021	Transport Canada recall 2021209 ^[2] Issued for the model year · Tires
15 Apr 2021	Transport Canada recall 2021228 ^[2] Issued for the model year · Electrical
29 Jul 2021	Transport Canada recall 2021466 ^[2] Issued for the model year · Fuel system
21 Jul 2022	Transport Canada recall 2022394 ^[2] Issued for the model year · Lights and instruments
23 Sep 2022	Transport Canada recall 2022538 ^[2] Issued for the model year · Lights and instruments
25 Oct 2026	Listed for sale, Whitby, ON ^[5] Nurse Chevrolet Cadillac · asking \$23,110
27 Oct 2026	Listing last updated ^[5] asking \$23,110

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 27 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

