Register entry, as of 27 October 2026 Listed for sale Record ID 68c9dc931a58

2017 Subaru Outback Premium +M/R

2.5 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4S4	BSCDC	8	H	3	355190
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Of America, Inc	Outback · 2.5 L	Verified	2017	United States	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.5 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Outback	Drive	Not in the decode
Trim	Premium +M/R	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/outback/2017

3 recalls listed by Transport Canada for this model year

Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Brakes

2022395 21 Jul 2022

Issue: On certain vehicles equipped with a manual transmission, a connector for the electronic parking brake (EPB) could disconnect. If this happens, you won't be able to apply the parking brake and the vehicle could roll away. If this happens and the parking brake is set, you won't be able release it. Note: This problem will cause the brake warning lamp to turn on or flash. Safety Risk: A parked vehicle that moves unexpectedly could increase the risk of an injury or a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the adapter cord connector for the electronic parking brake, and if necessary, install an additional retaining clip. To reduce the safety risk, Subaru recommends that you should park the vehicle in a flat location and leave the transmission in gear whenever possible until the recall repairs have been completed. Additionally, when parking uphill, the front wheels should be turned away from the curb and the shift lever should be placed into first gear. When parking downhill, the front wheels should be turned into the curb and the shift lever should be placed into reverse gear.

Structure

2016487 6 Oct 2016

On certain vehicles, the driver’s knee guard bracket may not have been properly aligned at the time of welding and may not have been properly attached to the steering beam. In a frontal crash where the driver is not wearing a seatbelt, the knee guard may not be able to restrain the occupant’s lower body as designed, which could increase the risk of injury to the driver. Correction: Knee guard welds will be inspected and repaired as necessary. Note: All vehicles are to be inspected and/or repaired prior to sale.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $18,500[5], $4,252 over the median of $14,248[4].



Lowest ask	$7,495
Middle half	$11,988 – $18,359
Median ask	$14,248
This car	$18,500

Same model year · 38 live listings · as of 27 Oct 2026

OTHER 2017 SUBARU OUTBACK LISTINGS [5]

Quebec, QC · 48,700 km	$17,950
Grande Prairie, AB · 143,736 km	$16,920
Sault Ste. Marie, ON · 166,499 km	$15,495
Vernon, BC · 141,037 km	$20,995
Lacombe, AB · 147,873 km	$20,199
Grande Prairie, AB · 143,736 km	$16,920

§4 EVENTS

2017	Model year 2017[1] Assembly plant United States
6 Oct 2016	Transport Canada recall 2016487[2] Issued for the model year · Structure
21 Jul 2022	Transport Canada recall 2022395[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label
16 Oct 2026	Listed for sale, Calgary, AB[5] Happy Corner Auto · asking $18,500
27 Oct 2026	Listing last updated[5] asking $18,500

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 38 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.