Register entry, as of 27 October 2026 Listed for sale Record ID e9d6ffa02034

2016 Subaru Outback Limited + MR + ES + NAVI

3.6 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4S4	BSFNC	0	G	3	346109
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Of America, Inc	Outback · 3.6 L	Verified	2016	United States	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.6 L, 6 cylinders
Make	Subaru	Fuel	Gasoline
Model	Outback	Drive	Not in the decode
Trim	Limited + MR + ES + NAVI	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/outback/2016

5 recalls listed by Transport Canada for this model year

Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Brakes

2022395 21 Jul 2022

Issue: On certain vehicles equipped with a manual transmission, a connector for the electronic parking brake (EPB) could disconnect. If this happens, you won't be able to apply the parking brake and the vehicle could roll away. If this happens and the parking brake is set, you won't be able release it. Note: This problem will cause the brake warning lamp to turn on or flash. Safety Risk: A parked vehicle that moves unexpectedly could increase the risk of an injury or a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the adapter cord connector for the electronic parking brake, and if necessary, install an additional retaining clip. To reduce the safety risk, Subaru recommends that you should park the vehicle in a flat location and leave the transmission in gear whenever possible until the recall repairs have been completed. Additionally, when parking uphill, the front wheels should be turned away from the curb and the shift lever should be placed into first gear. When parking downhill, the front wheels should be turned into the curb and the shift lever should be placed into reverse gear.

Steering

2016207 11 May 2016

On certain vehicles, steering column components may not have been manufactured to specification and therefore may not engage correctly, which could result in a loss of steering control and increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect, and if necessary, replace the steering column. Note: In the interim, owners are advised to not drive their vehicle until an inspection of the steering column has been completed.

Powertrain

2015555 23 Nov 2015

On certain vehicles, the nuts securing the propeller shaft to the rear differential may have not been tightened to specification during assembly and could loosen over time. This could cause the propeller shaft to come loose from the rear differential, which would result in excessive noise and may contact and eventually damage the fuel tank, which may result in a fuel leak. Fuel leakage, in the presence of an ignition source, could result in a fire causing injury and/or property damage. Correction: Dealers will inspect the nuts fastening the propeller shaft to the rear differential and tighten or replace the nuts and bolts as necessary.

Powertrain

2015358 6 Aug 2015

On certain vehicles, during the manufacturing process of pressing the seal cap onto the propeller shaft yoke, the seal cap may have been positioned incorrectly. This could result in the seal leaking transmission oil onto hot exhaust components, increasing the risk of fire resulting in injury and/or damage to property. Correction: Dealers will replace the propeller shaft assembly.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $15,995[5], $998 over the median of $14,997[4].

Lowest ask	$8,900
Middle half	$12,370 – $16,995
Median ask	$14,997
This car	$15,995

Same model year · 28 live listings · as of 27 Oct 2026

OTHER 2016 SUBARU OUTBACK LISTINGS [5]

Airdrie, AB · 211,089 km	$12,900
Terrebonne, QC · 180,950 km	$9,677
Orillia, ON · 158,600 km	$16,995
Toronto, ON · 154,426 km	$11,995
Edmonton, AB · 179,619 km	$14,500
Saint-Laurent, QC · 134,670 km	$12,495

§4 EVENTS

2016 **Model year 2016**[1]
Assembly plant United States

6 Aug 2015	Transport Canada recall 2015358[2] Issued for the model year · Powertrain
23 Nov 2015	Transport Canada recall 2015555[2] Issued for the model year · Powertrain
11 May 2016	Transport Canada recall 2016207[2] Issued for the model year · Steering
21 Jul 2022	Transport Canada recall 2022395[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label
11 Sep 2026	Listed for sale, Toronto, ON[5] Auto Rover Inc. · asking $15,995
27 Oct 2026	Listing last updated[5] asking $15,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 28 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.