Register entry, as of 27 October 2026 Listed for sale Record ID 84b6ea37e937

2018 Subaru Outback Limited+M/R+ES+NAVI

3.6 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4S4	BSFNC	7	J	3	258343
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Of America, Inc	Outback · 3.6 L	Verified	2018	Lafayette	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.6 L, 6 cylinders
Make	Subaru	Fuel	Gasoline
Model	Outback	Drive	4WD
Trim	Limited+M/R+ES+NAVI	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	Lafayette, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/outback/2018

4 recalls listed by Transport Canada for this model year

Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Fuel system

2021466 29 Jul 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Visual system

2018750 31 Dec 2018

Certain vehicles equipped with a built-in navigation system may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS 111) - Mirrors and Rear Visibility Systems. A software issue could prevent the centre display screen from turning on properly when the vehicle is started. If this occurs, the rearview image may not be displayed when the vehicle is put in reverse, which could reduce a driver's rear visibility. Correction: Dealers will reprogram the head unit software.

Fuel system

2018607 2 Nov 2018

On certain vehicles, the low fuel warning light may not turn on at the correct time to warn of a low fuel level. The driving range indicator in the multi-information display may also indicate a remaining distance-to-empty when the fuel tank is empty. While the low fuel warning light will eventually turn on and the fuel gauge will eventually display "E" (empty), if the driver continues to operate the vehicle based on the range indicator, the vehicle may run out of fuel, causing the engine to stall and increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will reprogram the combination meter (gauge cluster) software. Note: Until the recall repair is completed, drivers should ensure to refill the fuel tank before the fuel level is close to empty.

Listed for the model year, not checked against your VIN. Subaru confirms which apply.
Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $11,475[5], $5,467 under the median of $16,942[4].

Lowest ask	$10,991
Middle half	$15,496 – $19,442
Median ask	$16,942
This car	$11,475

Same model year · 46 live listings · as of 27 Oct 2026

OTHER 2018 SUBARU OUTBACK LISTINGS [5]

Boisbriand, QC · 290,858 km	$4,804
Trois-Rivières, QC · 108,700 km	$16,795
Courtenay, BC · 187,218 km	$21,995
Victoriaville, QC · 128,751 km	$17,995
Gloucester, ON · 112,585 km	$19,589
Courtenay, BC · 103,247 km	$26,448

§4 EVENTS

2018	Model year 2018[1] Assembly plant Lafayette, Indiana, United States
2 Nov 2018	Transport Canada recall 2018607[2] Issued for the model year · Fuel system
31 Dec 2018	Transport Canada recall 2018750[2] Issued for the model year · Visual system
29 Jul 2021	Transport Canada recall 2021466[2] Issued for the model year · Fuel system
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label

7 Oct 2026	Listed for sale, Boucherville, QC[5] Toyota De Boucherville · asking $11,475
27 Oct 2026	Listing last updated[5] asking $11,475

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 46 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.