Register entry, as of 28 October 2026 Listed for sale Record ID 94be02e6d95f

2021 Subaru Outback Limited+M/R+NAVI(HK)

AWD · Sport Utility Vehicle

VEHICLE IDENTIFICATION NUMBER [1]

4S4	BTHND	6	M	3	143996
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Of America, Inc	Outback	Verified	2021	Lafayette	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	Not in the decode
Make	Subaru	Fuel	Not in the decode
Model	Outback	Drive	AWD
Trim	Limited+M/R+NAVI(HK)	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	Lafayette, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/outback/2021

3 recalls listed by Transport Canada for this model year

Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Airbag

2024190 22 Mar 2024

Issue: On certain vehicles, an electrical component in the sensors for the occupant detection system (ODS) may not have been manufactured properly and could crack. Over time, moisture could enter the crack and cause a short circuit. If this happens, the passenger-front airbag may not deploy in a crash, even when a passenger is seated. Note: This problem would cause the SRS warning light to turn on in the instrument panel and the passenger airbag indicator light would display "OFF". Safety Risk: An airbag that does not work properly could increase the risk of injury to a passenger in a crash. Corrective Actions: Subaru will notify owners by mail and advise you to take your vehicle to a dealership to replace the ODS sensors in the front passenger seat. To reduce the safety risk, Subaru advises that you shouldn't use the front passenger seat if the SRS (airbag) warning light is on and the passenger airbag indicator light displays "OFF".

Electrical

2023607 9 Nov 2023

Issue: On certain vehicles, water could enter the inhibitor switch and cause it to fail. If this happens, the backup lamps may not turn on and the rearview camera image may not display when backing up. This could also cause the gear selection indicator in the instrument panel not to be displayed. Safety Risk: Backup lamps that don't work could cause others not to recognize when a vehicle is backing up. A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. These issues could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and advise you to take your vehicle to a dealership to replace the inhibitor switch.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $29,595[5], $2,595 over the median of $27,000[4].

Lowest ask	$18,999
Middle half	$24,368 – $29,974
Median ask	$27,000
This car	$29,595

Same model year · 38 live listings · as of 28 Oct 2026

OTHER 2021 SUBARU OUTBACK LISTINGS [5]

St. Catharines, ON · 149,728 km	$23,992
Dieppe, NB · 131,781 km	$23,995
Barrie, ON · 90,065 km	$27,000
Gloucester, ON · 163,418 km	$19,089
Rouyn-Noranda, QC · 82,801 km	$27,395
Pitt Meadows, BC · 75,011 km	$32,888

§4 EVENTS

2021	Model year 2021[1] Assembly plant Lafayette, Indiana, United States
9 Nov 2023	Transport Canada recall 2023607[2] Issued for the model year · Electrical
22 Mar 2024	Transport Canada recall 2024190[2] Issued for the model year · Airbag
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label
26 Oct 2026	Listed for sale, Lévis, QC[5] Levis Subaru · asking $29,595

28 Oct 2026	Listing last updated[5] asking $29,595

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 38 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.