Register entry, as of 27 October 2026 Listed for sale Record ID 374e66b9d92d

2023 Subaru Outback Touring

AWD · Sport Utility Vehicle

VEHICLE IDENTIFICATION NUMBER [1]

4S4	BTHPD	4	P	3	153492
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Of America, Inc	Outback	Verified	2023	Lafayette	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	Not in the decode
Make	Subaru	Fuel	Not in the decode
Model	Outback	Drive	AWD
Trim	Touring	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	Lafayette, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/outback/2023

3 recalls listed by Transport Canada for this model year

Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Electrical

2023607 9 Nov 2023

Issue: On certain vehicles, water could enter the inhibitor switch and cause it to fail. If this happens, the backup lamps may not turn on and the rearview camera image may not display when backing up. This could also cause the gear selection indicator in the instrument panel not to be displayed. Safety Risk: Backup lamps that don't work could cause others not to recognize when a vehicle is backing up. A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. These issues could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and advise you to take your vehicle to a dealership to replace the inhibitor switch.

Powertrain

2023521 21 Sep 2023

Issue: On certain vehicles, the bolts that attach the driveshaft center support brace could loosen. If this happens, the front end of the driveshaft could separate. Safety Risk: A driveshaft that separates could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and advise you to take your vehicle to a dealership to clean the bolt mounting surfaces for the driveshaft center support brace and install new bolts.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $30,995[5], $3,752 under the median of $34,747[4].



Lowest ask	$27,994
Middle half	$31,621 – $35,930
Median ask	$34,747
This car	$30,995

Same configuration · 10 live listings · as of 27 Oct 2026

OTHER 2023 SUBARU OUTBACK LISTINGS [5]

St-Léonard (Montréal), QC · 98,381 km	$30,495
Gloucester, ON · 47,515 km	$36,990
Ottawa, ON · 95,455 km	$28,281
Brossard, QC · 67,582 km	$29,993
Orangeville, ON · 38,300 km	$39,990
Burlington, ON · 61,219 km	$27,988

§4 EVENTS

2023	Model year 2023[1] Assembly plant Lafayette, Indiana, United States
21 Sep 2023	Transport Canada recall 2023521[2] Issued for the model year · Powertrain
9 Nov 2023	Transport Canada recall 2023607[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label
26 Oct 2026	Listed for sale, Notre-Dame-Des-Pins, QC[5] daniellessard.com · asking $30,995
27 Oct 2026	Listing last updated[5] asking $30,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 10 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.