Register entry, as of 28 October 2026 Listed for sale Record ID 867ea50d1d8a

# 2022 Subaru Ascent

2.4 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 4S4 | WMAHD | 9 | N | 3 | 401012 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Subaru Of America, Inc | Ascent · 2.4 L | Verified | 2022 | Lafayette | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 2.4 L, 4 cylinders |
| Make | Subaru | Fuel | Gasoline |
| Model | Ascent | Drive | AWD |
| Trim | Not in the decode | Maker | SUBARU OF AMERICA, INC |
| Body | Sport Utility Vehicle | Plant | Lafayette, Indiana, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/ascent/2022

**3** recalls listed by Transport Canada for this model year

### Label

2026329 7 Jul 2026

Issue: On certain vehicles, the compliance label lists an incorrect gross axle weight rating (GAWR). This could lead you to overload the vehicle, which could cause poor handling or a tire failure. Note: For the Forester model, this recall affects both gas and hybrid models. For the Crosstrek model, only the Crosstrek Hybrid model is affected. Safety Risk: Poor handling or a tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will mail a new compliance label to each owner. If you'd like help to install the label, you can contact a Subaru dealer to have it installed free of charge.

### Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

### Electrical

2022703 8 Dec 2022

Issue: On certain vehicles, the bolt for the ground terminal on the auxiliary heater may not have been properly tightened. As a result, the ground terminal and nearby parts could overheat and melt. Safety Risk: Wiring that overheats and melts could create the risk of a fire. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to replace the PTC (positive temperature coefficient) heater ground bolt. The ground wire and the connector holder will be replaced, if necessary. Subaru advises not remote start your vehicle using Subaru Starlink Connected Services (if equipped) or an aftermarket remote starter (if installed). Subaru also advises not leave the vehicle running while unattended, and that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $32,787[5], $3,208 under the median of $35,995[4].




| | |
|---|---|
| Lowest ask | $29,690 |
| Middle half | $32,787 – $36,955 |
| Median ask | $35,995 |
| This car | $32,787 |

Same configuration · 9 live listings · as of 28 Oct 2026

### OTHER 2022 SUBARU ASCENT LISTINGS [5]

| | |
|---|---|
| Surrey, BC · 133,632 km | $28,998 |
| Vancouver, BC · 54,400 km | $35,995 |
| Victoriaville, QC · 140,926 km | $21,495 |
| Vancouver, ON · 54,400 km | $35,999 |
| Richmond, BC · 54,400 km | $35,999 |
| North Vancouver, BC · 54,400 km | $35,995 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Lafayette, Indiana, United States |
| 8 Dec 2022 | Transport Canada recall 2022703[2]<br>Issued for the model year · Electrical |
| 15 Aug 2024 | Transport Canada recall 2024546[2]<br>Issued for the model year · Label |
| 7 Jul 2026 | Transport Canada recall 2026329[2]<br>Issued for the model year · Label |
| 26 Oct 2026 | Listed for sale, Chilliwack, BC[5]<br>Bannister GM Chilliwack · asking $32,787 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $32,787 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.