Register entry, as of 27 October 2026 Listed for sale Record ID 9c9d55fa6d60

2023 Subaru Ascent ONYX ES, SMART, M/R

2.4 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4S4	WMAHD	9	P	3	434675
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Subaru Of America, Inc	Ascent · 2.4 L	Verified	2023	Lafayette	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.4 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Ascent	Drive	AWD
Trim	ONYX ES, SMART, M/R	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	Lafayette, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/ascent/2023

4 recalls listed by Transport Canada for this model year

Label — 2026329 — 7 Jul 2026

Issue: On certain vehicles, the compliance label lists an incorrect gross axle weight rating (GAWR). This could lead you to overload the vehicle, which could cause poor handling or a tire failure. Note: For the Forester model, this recall affects both gas and hybrid models. For the Crosstrek model, only the Crosstrek Hybrid model is affected. Safety Risk: Poor handling or a tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will mail a new compliance label to each owner. If you'd like help to install the label, you can contact a Subaru dealer to have it installed free of charge.

Label — 2024546 — 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Powertrain — 2023521 — 21 Sep 2023

Issue: On certain vehicles, the bolts that attach the driveshaft center support brace could loosen. If this happens, the front end of the driveshaft could separate. Safety Risk: A driveshaft that separates could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and advise you to take your vehicle to a dealership to clean the bolt mounting surfaces for the driveshaft center support brace and install new bolts.

Tires

2023211 10 Apr 2023

Issue: On certain vehicles, the tires may have been damaged when they were mounted onto the rims in the factory. While you may not be able to see the damage, it could lead to a sudden tire failure. Note: This recall only affects factory-installed all-season tires on 20" wheels. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to replace the original equipment all-season tires. Subaru recommends that if the vehicle is equipped with winter tires, you should not re-install the original all-season tires, and contact your local dealer.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $36,643[5], the median[4].

Lowest ask	$30,276
Middle half	$33,498 – $38,494
Median ask	$36,643
This car	$36,643

Same configuration · 15 live listings · as of 27 Oct 2026

OTHER 2023 SUBARU ASCENT LISTINGS [5]

Bowmanville, ON · 58,480 km	$35,500
Newmarket, ON · 50,217 km	$35,893
Newmarket, ON · 80,738 km	$32,578
Newmarket, ON · 80,595 km	$32,998
Newmarket, ON · 101,219 km	$30,697
Newmarket, ON · 131,043 km	$30,276

§4 EVENTS

2023	Model year 2023[1] Assembly plant Lafayette, Indiana, United States
10 Apr 2023	Transport Canada recall 2023211[2] Issued for the model year · Tires
21 Sep 2023	Transport Canada recall 2023521[2] Issued for the model year · Powertrain
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label
7 Jul 2026	Transport Canada recall 2026329[2] Issued for the model year · Label

11 Sep 2026	Listed for sale, Lachute, QC[5] Lachute Subaru · asking $36,643
26 Oct 2026	Listing last updated[5] asking $36,643

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 15 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.