Register entry, as of 28 October 2026 Listed for sale Record ID d30c038d5109

2020 Subaru Ascent Limited 7+ES+KA+M/R+NAVI+H/K

2.4 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4S4	WMAPD	7	L	3	471493
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Subaru Of America, Inc	Ascent · 2.4 L	Verified	2020	Lafayette	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.4 L, 4 cylinders
Make	Subaru	Fuel	Gasoline
Model	Ascent	Drive	AWD
Trim	Limited 7+ES+KA+M/R+NAVI+H/K	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	Lafayette, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/subaru/ascent/2020

5 recalls listed by Transport Canada for this model year

Label

2026329 7 Jul 2026

Issue: On certain vehicles, the compliance label lists an incorrect gross axle weight rating (GAWR). This could lead you to overload the vehicle, which could cause poor handling or a tire failure. Note: For the Forester model, this recall affects both gas and hybrid models. For the Crosstrek model, only the Crosstrek Hybrid model is affected. Safety Risk: Poor handling or a tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Subaru will mail a new compliance label to each owner. If you'd like help to install the label, you can contact a Subaru dealer to have it installed free of charge.

Label

2024546 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Subaru has corrected the compliance label for all new vehicles.

Electrical

2022703 8 Dec 2022

Issue: On certain vehicles, the bolt for the ground terminal on the auxiliary heater may not have been properly tightened. As a result, the ground terminal and nearby parts could overheat and melt. Safety Risk: Wiring that overheats and melts could create the risk of a fire. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealership to replace the PTC (positive temperature coefficient) heater ground bolt. The ground wire and the connector holder will be replaced, if necessary. Subaru advises not remote start your vehicle using Subaru Starlink Connected Services (if equipped) or an aftermarket remote starter (if installed). Subaru also advises not leave the vehicle running while unattended, and that you should park it outdoors and away from other vehicles or structures until the recall repairs have been completed.

Powertrain

2021745 10 Dec 2021

Issue: On certain vehicles, a software problem in the transmission control unit (TCU) may cause the drive chain to slip or break. If this happens while the vehicle is in motion, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the transmission chain guide and update the TCU. If necessary, the transmission assembly will be replaced.

Steering

2021746 9 Dec 2021

Issue: On certain vehicles, the mounting holes for the tie rod ends were not manufactured correctly. As a result, the front tie rods may not fit properly. This could lead to damage during assembly and servicing. Over time, parts that do not fit correctly could separate and cause a loss of steering control. Safety Risk: A loss of steering control could create the risk of a crash. Corrective Actions: Subaru will notify owners by mail and instruct you to take your car to a dealer to replace the left and right steering knuckles, tie rod ends, and related hardware.

> Listed for the model year, not checked against your VIN. Subaru confirms which apply.
> Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.
> www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,999[5], $3,627 over the median of $23,372[4].

Lowest ask	$14,900
Middle half	$19,345 – $26,293
Median ask	$23,372
This car	$26,999

Same configuration · 12 live listings · as of 28 Oct 2026

OTHER 2020 SUBARU ASCENT LISTINGS [5]

Sarnia, ON · 149,191 km	$19,887
Grande Prairie, AB · 88,632 km	$27,952
Grande Prairie, AB · 88,632 km	$27,952
Newmarket, ON · 130,421 km	$20,911
Pembroke, ON · 130,275 km	$26,944
Québec, QC · 135,502 km	$20,595

§4 EVENTS

2020	Model year 2020[1] Assembly plant Lafayette, Indiana, United States
9 Dec 2021	Transport Canada recall 2021746[2] Issued for the model year · Steering
10 Dec 2021	Transport Canada recall 2021745[2] Issued for the model year · Powertrain
8 Dec 2022	Transport Canada recall 2022703[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024546[2] Issued for the model year · Label
21 Apr 2026	Listed for sale, Drummondville, QC[5] Drummondville Ford · asking $26,999
7 Jul 2026	Transport Canada recall 2026329[2] Issued for the model year · Label
28 Oct 2026	Listing last updated[5] asking $26,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 12 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.