

Register entry, as of 27 October 2026

Listed for sale

Record ID 2ba920f97ecb

2006 Subaru B9 Tribeca 5ST-M

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**4S4** **WX82C** **3** **6** **4** **400790**

WMI 1-3

Subaru Of America, Inc

DESCRIPTOR 4-8

B9 Tribeca · 3.0 L

CHECK 9

Verified

YEAR 10

2006

PLANT 11

United States

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2006	Engine	3.0 L, 6 cylinders
Make	Subaru	Fuel	Gasoline
Model	B9 Tribeca	Drive	AWD
Trim	5ST-M	Maker	SUBARU OF AMERICA, INC
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/subaru/b9-tribeca/2006

4 recalls listed by Transport Canada for this model year

Electrical

2019191 18 Apr 2019

Issue: A problem with certain replacement ignition switches may allow the key turn out of the "ON" position while driving. This could cause the engine to turn off suddenly. It could also cause the airbag system not to work properly in a crash. Note: This is a voluntary service campaign that is not being conducted under the requirements of the Motor Vehicle Safety Act. This problem only affects certain parts used for replacement of original parts. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An airbag system that does not work properly in a crash could cause an increased risk of injuries. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the ignition switch, and replace it as necessary.

Airbag

2017020 11 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Structure

2016048 1 Feb 2016

On certain vehicles, the primary and secondary hood latches could fail at the same time. If this were to occur, the hood could open unexpectedly while the vehicle is being driven. This could compromise the driver's ability to see the road and its users, as well as cause damage to the windshield. These issues could result in a crash causing injury and/or property damage. Correction: Dealers will inspect the hood latches, and either clean and lubricate or replace with the current style part. When parts are available, dealers will install revised hood latches.



Accessories

2012444 27 Dec 2012

On certain vehicles equipped with dealer-installed accessory puddle lights, a short circuit may develop causing the lights to melt and/or emit smoke. This could result in a fire causing property damage and/or injury. Correction: Dealers will install an additional fused wiring harness to protect against short circuits.

Listed for the model year, not checked against your VIN. Subaru confirms which apply.

Check your VIN with Subaru Canada or call a Subaru dealer with your VIN.

www.subaru.ca/WebPage.aspx?WebSiteID=282&WebPageID=21091

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$4,900^[5], \$702 over the median of \$4,198^[4].



Lowest ask \$3,495

Middle half \$3,846 – \$4,549

Median ask \$4,198

This car \$4,900

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2006 SUBARU B9 TRIBECA LISTINGS ^[5]

London, ON · 182,011 km

\$3,495

§4 EVENTS

2006	Model year 2006 ^[1] Assembly plant United States
27 Dec 2012	Transport Canada recall 2012444 ^[2] Issued for the model year · Accessories
1 Feb 2016	Transport Canada recall 2016048 ^[2] Issued for the model year · Structure
11 Jan 2017	Transport Canada recall 2017020 ^[2] Issued for the model year · Airbag
18 Apr 2019	Transport Canada recall 2019191 ^[2] Issued for the model year · Electrical
14 Aug 2026	Listed for sale, Richmond, BC ^[5] JC Motors · asking \$4,900
27 Oct 2026	Listing last updated ^[5] asking \$4,900



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

