Register entry, as of 26 November 2026 Listed for sale Record ID 6d6ab6474cf3

# 2015 Toyota Camry Hybrid

2.5 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 4T1 | BD1FK | 1 | F | U | 168321 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Toyota Motor Manufacturi… | Camry · 2.5 L | Verified | 2015 | United States | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2015 | Engine | 2.5 L, 4 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Camry | Drive | 4x2 |
| Trim | Hybrid | Maker | TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC. |
| Body | Sedan | Plant | United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/camry/2015

**2** recalls listed by Transport Canada for this model year

### Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

### Steering

2015103 11 Mar 2015


On certain vehicles, the circuit board for the electric power steering electronic control unit may be damaged. A damaged circuit board could result in sudden loss of steering power assist and would trigger a warning lamp to illuminate. A vehicle experiencing a loss of steering power assist would revert to a manual steering mode which would require greater driver effort, especially at low vehicle speeds. A loss of steering power assist could ultimately result in a crash causing property damage and/or personal injury. Correction: Dealers will replace inspect the electric power steering electronic control unit and, if affected, replace the electronic control unit with a new one.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $13,910[5], $1,078 under the median of $14,988[4].




| | |
|---|---|
| Lowest ask | $8,972 |
| Middle half | $12,972 – $16,924 |
| Median ask | $14,988 |
| This car | $13,910 |

Same model year · 23 live listings · as of 26 Nov 2026

### OTHER 2015 TOYOTA CAMRY LISTINGS [5]

| | |
|---|---|
| Mount Pearl, NL · 39,116 km | $9,925 |
| Ste-Julie, QC · 117,301 km | $14,988 |
| Vaudreuil-Dorion, QC · 118,331 km | $14,488 |
| Edmonton, AB · 157,761 km | $14,388 |
| Cochrane, AB · 100,909 km | $17,888 |
| Chicoutimi, QC · 147,259 km | $14,990 |

## §4 EVENTS

| | |
|---|---|
| 2015 | Model year 2015[1]<br>Assembly plant United States |
| 11 Mar 2015 | Transport Canada recall 2015103[2]<br>Issued for the model year · Steering |
| 24 Nov 2021 | Transport Canada recall 2021723[2]<br>Issued for the model year · Electrical |
| 19 Nov 2026 | Listed for sale, Edmonton, AB[5]<br>Bavaria BMW · asking $13,910 |
| 23 Nov 2026 | Listing last updated[5]<br>asking $13,910 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 23 live listings, as of 26 Nov 2026

[5] Live public dealer listings on Cardog, as of 26 Nov 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.