Register entry, as of 27 October 2026 Listed for sale Record ID 418e3cb91223

2014 Toyota Avalon

3.5 L, 6 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4T1	BK1EB	0	E	U	132903
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Avalon · 3.5 L	Verified	2014	Georgetown	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.5 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Avalon	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC.
Body	Sedan	Plant	Georgetown, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/avalon/2014

4 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Airbag

2020013 17 Jan 2020

Issue: On certain vehicles, the circuits within the airbag control module could be damaged in a crash. This could cause the airbags and seat belt pretensioners to not deploy in certain crashes. Safety Risk: Airbags or seat belts that do not work properly in a crash could create an increased risk of injury. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to install an electrical noise filter to prevent damage to the airbag control module.

Brakes

2015521 3 Nov 2015

On certain vehicles equipped with Pre-Collision System (PCS), the system could unexpectedly activate while operating the vehicle. Under certain situations, the system may interpret a steel joint or plate in the roadway as an obstacle, and the system may apply the service brake automatically. If the PCS applies unexpected braking force during normal vehicle operation when no impending collision object is present, it could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will disable the Pre-Collision System (PCS) as an interim measure, and when parts become available, will replace the PCS components with improved parts.

Fuel system

2014409 18 Sep 2014

On certain vehicles, the end cap on the right-hand side fuel delivery pipe, located in the engine compartment, could have been improperly welded at time of manufacture. This could result in a fuel leak which, in the presence of an ignition source, could result in a fire causing injury and/or property damage. Correction: Dealers will inspect the fuel delivery pipe and replace with a revised part if necessary.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $13,998[5], $500 over the median of $13,498[4].



Lowest ask	$12,999
Middle half	$13,249 – $13,748
Median ask	$13,498
This car	$13,998

Same model year · 2 live listings · as of 27 Oct 2026

OTHER 2014 TOYOTA AVALON LISTINGS [5]

Saint John, NB · 161,498 km	$12,999

§4 EVENTS

2014	Model year 2014[1] Assembly plant Georgetown, Kentucky, United States
18 Sep 2014	Transport Canada recall 2014409[2] Issued for the model year · Fuel system
3 Nov 2015	Transport Canada recall 2015521[2] Issued for the model year · Brakes
17 Jan 2020	Transport Canada recall 2020013[2] Issued for the model year · Airbag
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical

26 Oct 2026 **Listed for sale, Mont-Laurier, QC**[5]
KIA MONT LAURIER · asking $13,998

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.