

Register entry, as of 27 October 2026

Listed for sale

Record ID 6f3de46f53a9

2019 Toyota Avalon XLE/XSE/Touring/Ltd.

3.5 L, 6 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4T1 BZ1FB 0 K U 017966

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Avalon · 3.5 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

Georgetown

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.5 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Avalon	Drive	4x2
Trim	XLE/XSE/Touring/Ltd.	Maker	TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC.
Body	Sedan	Plant	Georgetown, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/avalon/2019

4 recalls listed by Transport Canada for this model year

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Fuel system

2020088 4 Mar 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recall SRC R95/SRC R96 (Transport Canada Recall No. 2020-005) Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Fuel system

2020005 13 Jan 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.



Airbag

2018547 5 Oct 2018

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 208 – Occupant Protection in Frontal Impacts and CMVSS 214 – Side Impact Protection. The airbag (SRS) control unit may incorrectly detect a fault in one or more of the front or side airbag impact sensors during vehicle start up. In the event of a crash where airbag deployment is required, this may result in the airbags not deploying as designed, increasing the risk of injury. Upon detection of a fault in the airbag system, multiple warning lights would activate, a warning buzzer would sound, and a warning message would display on the instrument panel display. Correction: Dealers will update the airbag control unit software. Note: This recall supersedes recall 2018-100. Vehicles repaired as part of the previous recall will require re-inspection and repair.


Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$33,495^[5], the median^[4].



Lowest ask	\$33,495
Middle half	\$33,495 – \$33,495
Median ask	\$33,495
This car	\$33,495

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Georgetown, Kentucky, United States
5 Oct 2018	Transport Canada recall 2018547 ^[2] Issued for the model year · Airbag
13 Jan 2020	Transport Canada recall 2020005 ^[2] Issued for the model year · Fuel system
4 Mar 2020	Transport Canada recall 2020088 ^[2] Issued for the model year · Fuel system
28 Oct 2020	Transport Canada recall 2020514 ^[2] Issued for the model year · Fuel system
17 Apr 2026	Listed for sale, Whitehouse, YT ^[5] Whitehorse Kia · asking \$33,495
27 Oct 2026	Listing last updated ^[5] asking \$33,495



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

