Register entry, as of 28 October 2026 Listed for sale Record ID 8a9b2b2e66d5

2026 Toyota Camry

2.5 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4T1	DAACK	3	T	U	793921
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Camry · 2.5 L	Verified	2026	Georgetown	Build sequence

§1 IDENTITY [1]

Model year	2026	Engine	2.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Camry	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC.
Body	Sedan	Plant	Georgetown, Kentucky, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/camry/2026

3 recalls listed by Transport Canada for this model year

Visual system

2026383 6 Aug 2026

Issue: On certain vehicles, a software problem could cause the combination meter in the instrument cluster not to display when the vehicle is started. As a result, the turn signals and hazard lights may not work. Additionally, you may not be able to see certain information about the vehicle, including warning lights, malfunction tell-tales and seat belt reminders. Note: This recall only affects vehicles equipped with a 7-inch display. Safety Risk: Turn signals that don't work may cause a person not to recognize when the driver intends to turn or change lanes and could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. A seat belt warning that doesn't work may not remind you to buckle your seat belt. Not wearing your seat belt can increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to update the combination meter software.

High voltage

2025693 16 Dec 2025

Issue: On certain vehicles, a bolt in the inverter assembly for the hybrid system may not have been tightened properly. As a result, the vehicle could enter a reduced power mode or lose power to the wheels. Additionally, if the bolt becomes loose in the inverter assembly and the ignition is on, it could cause a short circuit. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A short circuit can create the risk of a fire. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the hybrid inverter assembly bolt. The dealer will tighten the bolt or, if necessary, replace the inverter assembly.

Visual system

2025594 30 Oct 2025

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display. If this happens, the rearview image may not display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects certain vehicles equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to update the parking assist ECU software.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $40,203[5], $1,639 over the median of $38,564[4].

Lowest ask	$35,900
Middle half	$37,904 – $39,943
Median ask	$38,564
This car	$40,203

Same configuration · 50 live listings · as of 28 Oct 2026

OTHER 2026 TOYOTA CAMRY LISTINGS [5]

Sherbrooke, QC · 25 km	$37,956
Vancouver, BC · 50 km	$48,781
Terrebonne, QC · 10,294 km	$43,999
Hamilton, ON · 3 km	$48,516
Gatineau, QC · 25,527 km	$38,488
Newmarket, ON · 11,431 km	$49,990

§4 EVENTS

2026	Model year 2026[1] Assembly plant Georgetown, Kentucky, United States
30 Oct 2025	Transport Canada recall 2025594[2] Issued for the model year · Visual system
16 Dec 2025	Transport Canada recall 2025693[2] Issued for the model year · High voltage
6 Aug 2026	Transport Canada recall 2026383[2] Issued for the model year · Visual system
26 Oct 2026	Listed for sale, Owen Sound, ON[5] Baywest Toyota · asking $40,203

28 Oct 2026 Listing last updated[5]
asking $40,203

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 50 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.