Register entry, as of 28 October 2026 Listed for sale Record ID e81bfa474ede

# 2020 Toyota Camry SE

2.5 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 4T1 | G11AK | X | L | U | 983893 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Toyota Motor Manufacturi... | Camry · 2.5 L | Verified | 2020 | Georgetown | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 2.5 L, 4 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Camry | Drive | 4x2 |
| Trim | SE | Maker | TOYOTA MOTOR MANUFACTURING, KENTUCKY, INC. |
| Body | Sedan | Plant | Georgetown, Kentucky, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/camry/2020

**4** recalls listed by Transport Canada for this model year

### Airbag

2023684 20 Dec 2023

Issue: On certain vehicles, a sensor for the occupant classification system (OCS) may not have been manufactured properly. As a result, the sensor could short circuit and cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause a warning message to display on the instrument panel and the airbag indicator light would display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the OCS sensor.

### Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

### Engine

2020039 6 Feb 2020

Issue: On certain vehicles equipped with a 2.5-L 4-cylinder engine, the engine block may be porous. As a result, the engine block could crack and cause internal or external coolant leaks. This could cause engine overheating or internal engine damage and result in an engine failure. For non-hybrid vehicles, this could also result in a sudden loss of engine power while driving. Note: This problem may lead to engine noise, smoke, cause warning lights to turn on and/or cause an audible chime to sound before an engine failure. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Additionally, an engine failure could create the risk of a fire. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine block casting serial number. If the serial number is within the identified range, the dealer will replace the engine with a new one.

### Brakes

2019360 24 Jul 2019

Issue: On certain vehicles, a defect could cause the brake booster pump to fail. This could result in a loss of braking assist. If the failure occurs, the driver will be provided with both visual and audible warnings. It would also cause the Vehicle Stability Control system to turn off. Safety Risk: A loss of braking assist could cause extended stopping distances and increase the risk of a crash. A loss of Vehicle Stability Control would cause the vehicle to not meet the requirements of Canadian regulations, and could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect, and if necessary, replace the brake booster pump.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $26,995[5], $3,500 over the median of $23,495[4].

| | |
|---|---|
| Lowest ask | $16,995 |
| Middle half | $20,403 – $25,388 |
| Median ask | $23,495 |
| This car | $26,995 |

Same configuration · 9 live listings · as of 28 Oct 2026

#### OTHER 2020 TOYOTA CAMRY LISTINGS [5]

| | |
|---|---|
| Edmonton, AB · 66,661 km | $27,995 |
| Sherbrooke, QC · 35,626 km | $32,987 |
| Brampton, ON · 189,933 km | $21,888 |
| Newmarket, ON · 113,511 km | $21,888 |
| Mississauga, ON · 183,149 km | $17,888 |
| Laval, QC · 81,497 km | $27,495 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant Georgetown, Kentucky, United States |
| 24 Jul 2019 | Transport Canada recall 2019360[2]<br>Issued for the model year · Brakes |

| | |
|---|---|
| 6 Feb 2020 | Transport Canada recall 2020039[2]<br>Issued for the model year · Engine |
| 28 Oct 2020 | Transport Canada recall 2020514[2]<br>Issued for the model year · Fuel system |
| 20 Dec 2023 | Transport Canada recall 2023684[2]<br>Issued for the model year · Airbag |
| 26 Oct 2026 | Listed for sale, Salaberry-De-Valleyfield, QC[5]<br>Dandurand Automobiles · asking $26,995 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $26,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.