Register entry, as of 23 November 2026 Listed for sale Record ID 87d20324c87a

2007 Honda Odyssey EX

3.5 L, 6 cylinders · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN	RL384	8	7	B	511099
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co…	Odyssey · 3.5 L	Verified	2007	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Odyssey	Drive	Not in the decode
Trim	EX	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Minivan	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/odyssey/2007

4 recalls listed by Transport Canada for this model year

Fuel system — 2014076 — 14 Mar 2014

On certain vehicles, the fuel pump strainer could deteriorate and crack. This could result in a fuel smell and/or fuel leak. Leaking fuel, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will replace the fuel strainer cover.

Brakes — 2013381 — 4 Nov 2013

On certain vehicles, due to a defect in the Vehicle Stability Assist (VSA) system, the brakes may apply unexpectedly while the vehicle is being driven without the driver pressing on the brake pedal. If this were to occur, the brake lamps would also fail to illuminate. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will affect repairs.

Brakes — 2010364 — 22 Oct 2010

On certain vehicles, a seal in the brake master cylinder may be susceptible to damage which can result in a leak if certain conditions exist. The polymer content affects the amount of lubrication the brake fluid provides to brake system components that are exposed to brake fluid. If the brake fluid is replaced with a low polymer brake fluid, and the brake fluid is subsequently subjected to a manual brake fluid bleeding procedure, as opposed to an automated brake bleed procedure, it is possible for the seal at the end of the brake master cylinder primary circuit to become twisted within its retention groove. If this seal becomes twisted, it can result in a leak of a small amount of brake fluid each time the brake pedal is applied. Should a leak occur, after some time the driver will be alerted by the illumination of the low brake fluid indicator light on the meter panel before any effect on braking performance results. If the driver continues to drive the vehicle without refilling the brake fluid reservoir, the vehicle will eventually exhibit a soft or spongy brake pedal feel, requiring more stroke to achieve equivalent braking force. Eventually, if this continues un-remedied, braking performance will be affected, and will finally result in a low pedal and a loss of one braking circuit. Correction: Dealers will replace the brake master cylinder seal cup and the master power assembly if brake fluid has leaked.

Brakes 2010079 16 Mar 2010

On certain vehicles, during the self-check process that occurs shortly after each time the engine is started, the self-diagnostic software for the Vehicle Stability Assist (VSA) brake modulator causes a condition that can allow air to enter the modulator pump. Over time, and after starting the engine numerous times, it is possible for enough air to enter the system to change the brake pedal feel and affect braking performance. Reduced braking performance could lead to a crash causing property damage, personal injury or death. Correction: Dealers will remove existing air in the brake system then apply sealant and caps to the VSA modulator to prevent air from entering the brake system.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $8,488[5], $1,242 over the median of $7,246[4].



Lowest ask	$2,999
Middle half	$5,254 – $8,546
Median ask	$7,246
This car	$8,488

Same model year · 4 live listings · as of 23 Nov 2026

OTHER 2007 HONDA ODYSSEY LISTINGS [5]

Nanaimo, BC · 313,014 km	$2,999
Bolton, ON · 219,181 km	$8,721
Oakville, ON · 315,245 km	$6,005

§4 EVENTS

2007	Model year 2007[1] Assembly plant Lincoln, Alabama, United States
16 Mar 2010	Transport Canada recall 2010079[2] Issued for the model year · Brakes
22 Oct 2010	Transport Canada recall 2010364[2] Issued for the model year · Brakes
4 Nov 2013	Transport Canada recall 2013381[2] Issued for the model year · Brakes
14 Mar 2014	Transport Canada recall 2014076[2] Issued for the model year · Fuel system
26 Oct 2026	Listed for sale, Edmonton, AB[5] Rally Subaru · asking $8,488

22 Nov 2026 **Listing last updated**[5]
asking $8,488

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 4 live listings, as of 23 Nov 2026
[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.