Register entry, as of 28 October 2026 Listed for sale Record ID 934d8a0a06b6

2015 Honda Odyssey EXL/EXL-N/EXL-R

3.5 L, 6 cylinders · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN	RL5H6	0	F	B	511433
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Odyssey · 3.5 L	Verified	2015	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Odyssey	Drive	Not in the decode
Trim	EXL/EXL-N/EXL-R	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Minivan	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/odyssey/2015

4 recalls listed by Transport Canada for this model year

Seats and restraints

2018128 13 Mar 2018

On certain vehicles, the seat recliner mechanism for the second row left (driver's) side seat may have a manufacturing error. If the second row left side seat walk-in feature (which folds the seatback and slides the seat forward for access to the third row) is operated while the seat is in the full recline position, the recliner cam could over rotate. When the seatback is returned to an upright position, there is a potential for the seatback to stay in unlocked position or unexpectedly unlock without engaging the lever. In the event of crash, an unlocked seatback could increase the risk of injury to the seat occupant. Correction: Dealers will test the seat to confirm proper operation. If the seat recliner is found to be operating properly, a stopper bracket (which limits the rotation of the cam) will be installed on the seat recliner mechanism. In cases where the seatback does not function properly, dealers will replace the seatback frame assembly and a stopper bracket will be installed and proper operation will be verified.

Seats and restraints

2017567 17 Nov 2017

On certain vehicles, the rear outboard strikers of the second row outboard (outer) seats have a collar to define two set positions. If an outboard seat is positioned over the collar while attaching the seat to the vehicle floor, the seat will not latch properly to the striker. An unlatched second row outboard seat could tip forward during moderate to heavy braking, which could increase the risk of injury to the seat occupant. Correction: Dealers will install a second row seat striker bracket and a warning label on both second row outer seats. Additionally, dealers will also place supplemental owner information cards in the glove box.

Seats and restraints

2016645 20 Dec 2016

On certain vehicles, the lever on the second row outboard seats, which allows access to the third row seat, may stay in the unlocked position after returning the seat to its normal seating position. An unlocked second row outboard seat could increase the risk of injury to the seat occupant in the event of a crash. Correction : Dealers will install an additional bracket and spring to the second row outboard seat adjuster to ensure proper engagement of the walk-in lever.

Label

2015598 18 Dec 2015

Certain vehicles may not comply with Canadian Motor Vehicle Safety Regulations. The compliance label may bear incorrect rear Gross Axle Weight Rating (GAWR) information (lower than the vehicle's actual rear GAWR). Correction: A production change has been undertaken to remedy this technical non-compliance condition. No corrective recall action is required as the technical non-compliance conditions are deemed to be non-safety related.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $12,995[5], $2,252 under the median of $15,247[4].

Lowest ask	$10,999
Middle half	$13,998 – $16,614
Median ask	$15,247
This car	$12,995

Same model year · 24 live listings · as of 28 Oct 2026

OTHER 2015 HONDA ODYSSEY LISTINGS [5]

Mississauga, ON · 119,207 km	$16,488
Leamington, ON · 119,207 km	$16,488
Ottawa, ON · 189,619 km	$13,988
Essex, ON · 119,207 km	$16,488
Toronto, ON · 119,207 km	$16,488
Windsor, ON · 119,207 km	$16,488

§4 EVENTS

2015	Model year 2015[1] Assembly plant Lincoln, Alabama, United States
18 Dec 2015	Transport Canada recall 2015598[2] Issued for the model year · Label
20 Dec 2016	Transport Canada recall 2016645[2] Issued for the model year · Seats and restraints
17 Nov 2017	Transport Canada recall 2017567[2] Issued for the model year · Seats and restraints
13 Mar 2018	Transport Canada recall 2018128[2] Issued for the model year · Seats and restraints

26 Oct 2026	Listed for sale, Montreal, QC[5] mpautomtl.com · asking $12,995
27 Oct 2026	Listing last updated[5] asking $12,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 24 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.