Register entry, as of 27 October 2026 Listed for sale Record ID 5ac7de365561

2018 Honda Odyssey EX-L w/ NAVI / EX-L w/ RES

3.5 L, 6 cylinders · 4x2 · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN	RL6H6	X	J	B	506173
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Odyssey · 3.5 L	Verified	2018	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Odyssey	Drive	4x2
Trim	EX-L w/ NAVI / EX-L w/ RES	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Minivan	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/odyssey/2018

15 recalls listed by Transport Canada for this model year

Visual system

2026326 2 Jul 2026

Issue: On certain vehicles, the recall repairs completed by a Honda dealer during recall O38 (Transport Canada recall no. 2020-345) may not be effective. As a result, certain vehicles require a second repair. On certain vehicles, moisture could enter the rearview camera and cause it not to work properly. If this happens, the rearview image may be distorted or not display at all. Also, the camera image may not appear in certain bright light conditions. Note: This recall replaces recall O38 (Transport Canada recall no. 2020-345). Vehicles that were repaired under that recall also require this repair. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealer to replace the rearview camera.

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Seats and restraints

2026181 9 Apr 2026

Issue: On certain vehicles, under certain conditions, a software problem could cause the side airbag(s) and side curtain airbag(s) to inflate unexpectedly. Safety Risk: An airbag that deploys without a crash could create a risk of injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to reprogram or replace the supplemental restraint system (SRS) electronic control unit (ECU), as necessary.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Visual system

2023350 15 Jun 2023

Issue: On certain vehicles, the terminals on the coaxial cable for the audio display unit may not have been manufactured correctly. As a result, the audio display unit could lose its connection, and the rearview camera image may not display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the media oriented systems transport (MOST) cable harness, and install a cover over the audio display unit connector.

9 more on the model-year record, cardog.app/tools/recalls/honda/odyssey/2018

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 16 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $23,995[5], $903 under the median of $24,898[4].

Lowest ask	$15,888
Middle half	$22,921 – $28,494
Median ask	$24,898
This car	$23,995

Same configuration · 22 live listings · as of 27 Oct 2026

OTHER 2018 HONDA ODYSSEY LISTINGS [5]

Trois-Rivières, QC · 145,614 km	$23,988
Medicine Hat, AB · 87,533 km	$32,708
Markham, ON · 207,469 km	$15,888
Markham, ON · 126,928 km	$23,388

Oshawa, ON · 73,914 km	$28,993
Cornwall, ON · 63,485 km	$31,900

§4 EVENTS

2018	Model year 2018[1] Assembly plant Lincoln, Alabama, United States
27 Jun 2017	Transport Canada recall 2017317[2] Issued for the model year · Seats and restraints
1 Nov 2018	Transport Canada recall 2018602[2] Issued for the model year · Brakes
13 Nov 2018	Transport Canada recall 2018622[2] Issued for the model year · Structure
11 Apr 2019	Transport Canada recall 2019180[2] Issued for the model year · Powertrain
6 Feb 2020	Transport Canada recall 2020042[2] Issued for the model year · Electrical
28 Jul 2020	Transport Canada recall 2020344[2] Issued for the model year · Visual system
29 Jul 2020	Transport Canada recall 2020343[2] Issued for the model year · Structure
19 Jan 2021	Transport Canada recall 2021012[2] Issued for the model year · Fuel system
9 Mar 2023	Transport Canada recall 2023127[2] Issued for the model year · Seats and restraints
15 Jun 2023	Transport Canada recall 2023350[2] Issued for the model year · Visual system
18 Dec 2023	Transport Canada recall 2023679[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262[2] Issued for the model year · Fuel system
9 Apr 2026	Transport Canada recall 2026181[2] Issued for the model year · Seats and restraints
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
2 Jul 2026	Transport Canada recall 2026326[2] Issued for the model year · Visual system
26 Oct 2026	Listed for sale, Steinbach, MB[5] Loeppky Auto Sales · asking $23,995

27 Oct 2026	Listing last updated[5] asking $23,995

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 22 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.