Register entry, as of 17 November 2026 Listed for sale Record ID e8c4a8ceea1c

2011 Honda Pilot Touring

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN	YF4H9	8	B	B	504599
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co…	Pilot · 3.5 L	Verified	2011	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Pilot	Drive	4WD
Trim	Touring	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/pilot/2011

4 recalls listed by Transport Canada for this model year

Airbag

2018523 27 Sep 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator.

Airbag

2013018 18 Jan 2013

On certain vehicles, the airbag cover may not have been adequately secured to the driver's airbag module. As a result, the airbag may deploy with an irregular shape, or the cover may detach during deployment. Failure of the airbag to deploy in the designed manner during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect and, if necessary, replace the driver's airbag module.

Seats and restraints

2011334 9 Sep 2011

On certain vehicles, the driver and front passenger seatbelt webbing may have been incorrectly manufactured. As a result, the seatbelt may detach from the anchor webbing during a crash. Failure of the seatbelt to restrain the seat occupant as intended would increase the risk of personal injury during a crash. Correction: Dealers will inspect and, if necessary, replace the driver and front passenger seatbelts.

Suspension

2010451 17 Dec 2010


On certain vehicles, the front axle spindle nuts, as well as the bolts that secure the front suspension damper brackets to the steering knuckles, may not have been tightened properly during vehicle assembly. If the spindle nuts or the front damper bracket bolts loosen and fall out the front suspension may collapse, which could cause a loss of vehicle control. A loss of vehicle control could result in a crash causing property damage and/or personal injury. Correction: Dealers will inspect and replace the bolts that were not torqued to specifications.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,995[5], $3,248 over the median of $11,747[4].



Lowest ask	$6,900
Middle half	$8,745 – $13,986
Median ask	$11,747
This car	$14,995

Same model year · 8 live listings · as of 17 Nov 2026

OTHER 2011 HONDA PILOT LISTINGS [5]

Brampton, ON · 135,860 km	$13,499
Calgary, AB · 243,513 km	$13,650
Sainte-Rose, QC · 256,298 km	$6,900
Calgary, AB · 243,513 km	$13,650
Calgary, AB · 243,513 km	$13,650
Calgary, AB · 243,513 km	$13,650

§4 EVENTS

2011	Model year 2011[1] Assembly plant Lincoln, Alabama, United States
17 Dec 2010	Transport Canada recall 2010451[2] Issued for the model year · Suspension
9 Sep 2011	Transport Canada recall 2011334[2] Issued for the model year · Seats and restraints
18 Jan 2013	Transport Canada recall 2013018[2] Issued for the model year · Airbag
27 Sep 2018	Transport Canada recall 2018523[2] Issued for the model year · Airbag

22 Sep 2026	Listed for sale, Burnaby, BC[5] Enix Motor Sport Ltd · asking $14,995
16 Nov 2026	Listing last updated[5] asking $14,995

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 8 live listings, as of 17 Nov 2026

[5] Live public dealer listings on Cardog, as of 17 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.