Register entry, as of 18 November 2026 Listed for sale Record ID 603837f58b68

# 2020 Honda Pilot ELITE

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5FN | YF6H0 | 9 | L | B | 504013 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| American Honda Motor Co... | Pilot · 3.5 L | Verified | 2020 | Lincoln | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 3.5 L, 6 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Pilot | Drive | 4WD |
| Trim | ELITE | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Sport Utility Vehicle | Plant | Lincoln, Alabama, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/pilot/2020

**12** recalls listed by Transport Canada for this model year

### Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Visual system

2024761 13 Dec 2024

Issue: Under certain conditions, a software problem could cause the wrong view mode to display when the transmission is shifted into reverse. As a result, the rearview camera image may not appear correctly on the display screen. Canadian regulations allow only certain view modes to be displayed when the vehicle is reversing. Note: Vehicles that received a software update previously under a Honda product update, campaign no. P01 - 'Incorrect Rear View Camera View Mode', don't require this repair. Safety Risk: A rearview camera image that doesn't display the correct view mode could reduce a driver's field of view behind the vehicle. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and have sent a wireless over-the-air software update to eligible vehicles to update the vehicle software. Alternatively, you may schedule an appointment to have the update performed at a Honda dealership.

### Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

### Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

6 more on the model-year record, cardog.app/tools/recalls/honda/pilot/2020

> Listed for the model year, not checked against your VIN. Honda confirms which apply. Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $25,998[5], the median[4].




| | |
|---|---|
| Lowest ask | $12,498 |
| Middle half | $22,749 – $31,992 |
| Median ask | $25,998 |
| This car | $25,998 |

Same model year · 27 live listings · as of 18 Nov 2026

### OTHER 2020 HONDA PILOT LISTINGS [5]

| | |
|---|---|
| Cochrane, AB · 189,981 km | $27,888 |
| Moncton, NB · 70,617 km | $36,491 |
| Weyburn, SK · 99,945 km | $34,998 |
| Boucherville, QC · 139,929 km | $25,990 |
| Calgary, AB · 93,990 km | $38,499 |
| London, ON · 146,035 km | $24,995 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant Lincoln, Alabama, United States |
| 6 Feb 2020 | Transport Canada recall 2020041[2]<br>Issued for the model year · Label |
| 28 Jul 2020 | Transport Canada recall 2020346[2]<br>Issued for the model year · Visual system |
| 28 Jul 2020 | Transport Canada recall 2020344[2]<br>Issued for the model year · Visual system |
| 11 Mar 2021 | Transport Canada recall 2021139[2]<br>Issued for the model year · Tires |
| 16 Mar 2023 | Transport Canada recall 2023136[2]<br>Issued for the model year · Visual system |
| 15 Jun 2023 | Transport Canada recall 2023350[2]<br>Issued for the model year · Visual system |
| 18 Dec 2023 | Transport Canada recall 2023679[2]<br>Issued for the model year · Fuel system |
| 1 Feb 2024 | Transport Canada recall 2024059[2]<br>Issued for the model year · Airbag |
| 6 May 2024 | Transport Canada recall 2024262[2]<br>Issued for the model year · Fuel system |
| 13 Dec 2024 | Transport Canada recall 2024761[2]<br>Issued for the model year · Visual system |
| 21 May 2026 | Transport Canada recall 2026251[2]<br>Issued for the model year · Seats and restraints |
| 4 Jun 2026 | Transport Canada recall 2026275[2]<br>Issued for the model year · Structure |
| 3 Nov 2026 | Listed for sale, Bolton, ON[5]<br>Bolton Honda · asking $25,998 |
| 18 Nov 2026 | Listing last updated[5]<br>asking $25,998 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 27 live listings, as of 18 Nov 2026
[5] Live public dealer listings on Cardog, as of 18 Nov 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.