Register entry, as of 28 October 2026 Listed for sale Record ID 1ddf96990e3c

2016 Honda Pilot EXL

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN	YF6H5	2	G	B	510799
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Pilot · 3.5 L	Verified	2016	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Pilot	Drive	4WD
Trim	EXL	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/pilot/2016

5 recalls listed by Transport Canada for this model year

Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

Engine

2023603 8 Nov 2023

Issue: On certain vehicles equipped with a V6 engine, the connecting rod bearings could wear prematurely and become damaged. If this happens, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Safety Risk: An engine failure could cause a sudden loss of power and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect the engine. If damage is found, the dealer will replace the necessary parts.

Structure

2021725 25 Nov 2021

Issue: On certain vehicles, the hood latch striker could separate from the hood. If this happens, the hood could open while driving. Note: A loose or vibrating hood may be a warning that the hood latch is failing. Safety Risk: A hood that opens suddenly while driving could block the driver's view and increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the hood latch striker. Depending on its condition, a striker support plate will be installed, or if necessary, the hood will be replaced.

Fuel system

2016278 3 Jun 2016

On certain vehicles, the fuel tank may have received insufficient welds during manufacturing. Over time, the insufficient welds may separate and allow for fuel leakage. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or property damage. Correction: Dealers will replace the fuel tank.

Brakes

2015474 16 Oct 2015

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 135 - Brake Systems and Canada Motor Vehicle Safety Standard 126 - Electronic Stability Control Systems. Due to a software error in the instrument cluster, Vehicle Stability Assist (VSA), ABS and BRAKE warning lamps may not illuminate under certain conditions, which fails to meet the requirements of the standard. Failure of these lights to illuminate could increase the risk of a crash causing injury and/or damage to property. Note: The warning light will illuminate with next key cycle. Correction: Dealers will update the instrument cluster software.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,750[5], $4,150 under the median of $18,900[4].

Lowest ask	$12,500
Middle half	$15,888 – $21,995
Median ask	$18,900
This car	$14,750

Same configuration · 9 live listings · as of 28 Oct 2026

OTHER 2016 HONDA PILOT LISTINGS [5]

Airdrie, AB · 92,983 km	$24,500
Newmarket, ON · 194,311 km	$14,995
Grande Prairie, AB · 94,123 km	$24,995
London, ON · 103,488 km	$21,995
Ottawa, ON · 75,128 km	$21,857
Montréal Nord, QC · 112,000 km	$20,895

§4 EVENTS

2016	Model year 2016[1] Assembly plant Lincoln, Alabama, United States
16 Oct 2015	Transport Canada recall 2015474[2] Issued for the model year · Brakes
3 Jun 2016	Transport Canada recall 2016278[2] Issued for the model year · Fuel system

25 Nov 2021	Transport Canada recall 2021725[2] Issued for the model year · Structure
8 Nov 2023	Transport Canada recall 2023603[2] Issued for the model year · Engine
4 Jun 2026	Transport Canada recall 2026275[2] Issued for the model year · Structure
21 Oct 2026	Listed for sale, Toronto, ON[5] Motorland Auto Sales Inc. · asking $14,750
28 Oct 2026	Listing last updated[5] asking $14,750

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.