Register entry, as of 17 November 2026 Listed for sale Record ID 7d76fa0f4c21

2021 Honda Pilot BLACK

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN	YF6H7	1	M	B	504005
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Pilot · 3.5 L	Verified	2021	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Pilot	Drive	4WD
Trim	BLACK	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/pilot/2021

10 recalls listed by Transport Canada for this model year

Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Visual system

2024761 13 Dec 2024

Issue: Under certain conditions, a software problem could cause the wrong view mode to display when the transmission is shifted into reverse. As a result, the rearview camera image may not appear correctly on the display screen. Canadian regulations allow only certain view modes to be displayed when the vehicle is reversing. Note: Vehicles that received a software update previously under a Honda product update, campaign no. P01 - 'Incorrect Rear View Camera View Mode', don't require this repair. Safety Risk: A rearview camera image that doesn't display the correct view mode could reduce a driver's field of view behind the vehicle. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and have sent a wireless over-the-air software update to eligible vehicles to update the vehicle software. Alternatively, you may schedule an appointment to have the update performed at a Honda dealership.

Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Brakes

2023365 29 Jun 2023

Issue: On certain vehicles, the brake master cylinder could separate from the brake booster. If this happens, braking could be reduced or you could experience a complete loss of brakes. Safety Risk: Reduced braking or a loss of brakes can increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect the brake master cylinder and brake booster. The dealer will inspect for any missing nuts and damaged brake booster parts and replace them as necessary.

Visual system

2023350 15 Jun 2023

Issue: On certain vehicles, the terminals on the coaxial cable for the audio display unit may not have been manufactured correctly. As a result, the audio display unit could lose its connection, and the rearview camera image may not display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the media oriented systems transport (MOST) cable harness, and install a cover over the audio display unit connector.

4 more on the model-year record, cardog.app/tools/recalls/honda/pilot/2021

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $31,500[5], $205 over the median of $31,295[4].



Lowest ask	$22,990
Middle half	$28,995 – $34,482
Median ask	$31,295
This car	$31,500

Same configuration · 17 live listings · as of 17 Nov 2026

OTHER 2021 HONDA PILOT LISTINGS [5]

Levis, QC · 227,245 km	$18,995
Calgary, AB · 119,011 km	$35,395
Calgary, AB · 119,011 km	$35,395
Cochrane, AB · 95,018 km	$37,888
Fort McMurray, AB · 119,011 km	$35,395
Calgary, AB · 119,011 km	$35,395

§4 EVENTS

2021	Model year 2021[1] Assembly plant Lincoln, Alabama, United States
28 Jul 2020	Transport Canada recall 2020346[2] Issued for the model year · Visual system
28 Jul 2020	Transport Canada recall 2020344[2] Issued for the model year · Visual system
20 Nov 2020	Transport Canada recall 2020560[2] Issued for the model year · Tires
16 Mar 2023	Transport Canada recall 2023136[2] Issued for the model year · Visual system
15 Jun 2023	Transport Canada recall 2023350[2] Issued for the model year · Visual system
29 Jun 2023	Transport Canada recall 2023365[2] Issued for the model year · Brakes
1 Feb 2024	Transport Canada recall 2024059[2] Issued for the model year · Airbag
13 Dec 2024	Transport Canada recall 2024761[2] Issued for the model year · Visual system
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
4 Jun 2026	Transport Canada recall 2026275[2] Issued for the model year · Structure
25 Oct 2026	Listed for sale, St. Catharines, ON[5] CMH AUTO SUPERSTORE · asking $31,500
17 Nov 2026	Listing last updated[5] asking $31,500

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 17 live listings, as of 17 Nov 2026
[5] Live public dealer listings on Cardog, as of 17 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.