Register entry, as of 17 November 2026 Listed for sale Record ID a8b9c27456bc

2017 Honda Pilot EXL-N

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN	YF6H7	7	H	B	507870
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Pilot · 3.5 L	Verified	2017	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Pilot	Drive	4WD
Trim	EXL-N	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/pilot/2017

4 recalls listed by Transport Canada for this model year

Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Structure 2021725 25 Nov 2021

Issue: On certain vehicles, the hood latch striker could separate from the hood. If this happens, the hood could open while driving. Note: A loose or vibrating hood may be a warning that the hood latch is failing. Safety Risk: A hood that opens suddenly while driving could block the driver's view and increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the hood latch striker. Depending on its condition, a striker support plate will be installed, or if necessary, the hood will be replaced.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,999[5], $2,890 under the median of $23,889[4].



Lowest ask	$10,900
Middle half	$17,736 – $24,999
Median ask	$23,889
This car	$20,999

Same configuration · 14 live listings · as of 17 Nov 2026

OTHER 2017 HONDA PILOT LISTINGS [5]

Moncton, NB · 101,710 km	$25,991
Ottawa, ON · 264,074 km	$10,900
Guelph, ON · 154,322 km	$20,998
North Vancouver, BC · 97,812 km	$26,900
Regina, SK · 137,600 km	$24,988
Granby, QC · 142,490 km	$20,459

§4 EVENTS

2017	Model year 2017[1] Assembly plant Lincoln, Alabama, United States
25 Nov 2021	Transport Canada recall 2021725[2] Issued for the model year · Structure
18 Dec 2023	Transport Canada recall 2023679[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262[2] Issued for the model year · Fuel system
4 Jun 2026	Transport Canada recall 2026275[2] Issued for the model year · Structure

6 Oct 2026	Listed for sale, Laval, QC[5] Honda De Laval · asking $20,999
16 Nov 2026	Listing last updated[5] asking $20,999

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 14 live listings, as of 17 Nov 2026

[5] Live public dealer listings on Cardog, as of 17 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.