

Register entry, as of 29 October 2026

Listed for sale

Record ID 49540b0c1aad

# 2020 Honda Passport EXL

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**5FN** **YF8H5** **8** **L** **B** **501675**

WMI 1-3

American Honda Motor Co...

DESCRIPTOR 4-8

Passport · 3.5 L

CHECK 9

Verified

YEAR 10

2020

PLANT 11

Lincoln

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                 |
|------------|-----------------------|--------|---------------------------------|
| Model year | 2020                  | Engine | 3.5 L, 6 cylinders              |
| Make       | Honda                 | Fuel   | Gasoline                        |
| Model      | Passport              | Drive  | 4WD                             |
| Trim       | EXL                   | Maker  | AMERICAN HONDA MOTOR CO., INC.  |
| Body       | Sport Utility Vehicle | Plant  | Lincoln, Alabama, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/honda/passport/2020](https://cardog.app/tools/recalls/honda/passport/2020)

## 9 recalls listed by Transport Canada for this model year

### Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Visual system

2024761 13 Dec 2024

Issue: Under certain conditions, a software problem could cause the wrong view mode to display when the transmission is shifted into reverse. As a result, the rearview camera image may not appear correctly on the display screen. Canadian regulations allow only certain view modes to be displayed when the vehicle is reversing. Note: Vehicles that received a software update previously under a Honda product update, campaign no. P01 - 'Incorrect Rear View Camera View Mode', don't require this repair. Safety Risk: A rearview camera image that doesn't display the correct view mode could reduce a driver's field of view behind the vehicle. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and have sent a wireless over-the-air software update to eligible vehicles to update the vehicle software. Alternatively, you may schedule an appointment to have the update performed at a Honda dealership.



**Airbag**

2024059 1 Feb 2024

**Issue:** On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. **Note:** If the weight sensor fails, the SRS warning light would turn on in the instrument panel. **Safety Risk:** An airbag system that doesn't work properly could increase the risk of injury in a crash. **Corrective Actions:** Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

**Visual system**

2023350 15 Jun 2023

**Issue:** On certain vehicles, the terminals on the coaxial cable for the audio display unit may not have been manufactured correctly. As a result, the audio display unit could lose its connection, and the rearview camera image may not display when the transmission is shifted into reverse gear. **Safety Risk:** A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. **Corrective Actions:** Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the media oriented systems transport (MOST) cable harness, and install a cover over the audio display unit connector.

**Visual system**

2023136 16 Mar 2023

**Issue:** On certain vehicles, the side mirror glass may not be attached properly. As a result, the mirror glass could vibrate or fall off. **Safety Risk:** A missing mirror will reduce rear visibility and could increase the risk of a crash. **Corrective Actions:** Honda will notify owners by mail. Due to a parts supply issue, Honda advises that you should only take your vehicle to a dealership if the mirror is loose, vibrating or has fully detached. Honda will send you a second notice when the replacement parts are available, and instruct you to take your vehicle to a dealership to replace the glass on both side mirrors.


3 more on the model-year record, [cardog.app/tools/recalls/honda/passport/2020](https://cardog.app/tools/recalls/honda/passport/2020)

Listed for the model year, not checked against your VIN. Honda confirms which apply.  
Check your VIN with Honda Canada or call a Honda dealer with your VIN.  
[www.honda.ca/en/recalls](https://www.honda.ca/en/recalls)

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$27,323<sup>[5]</sup>, \$3,174 under the median of \$30,497<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$21,995            |
| Middle half | \$27,891 – \$31,396 |
| Median ask  | \$30,497            |
| This car    | \$27,323            |

Same model year · 14 live listings · as of 29 Oct 2026

**OTHER 2020 HONDA PASSPORT LISTINGS** <sup>[5]</sup>

|                             |          |
|-----------------------------|----------|
| Mississauga, ON · 97,919 km | \$30,499 |
| Leamington, ON · 97,919 km  | \$30,499 |
| Essex, ON · 97,919 km       | \$30,499 |
| Toronto, ON · 97,919 km     | \$30,499 |
| Windsor, ON · 97,919 km     | \$30,499 |
| Listowel, ON · 134,565 km   | \$29,595 |



## §4 EVENTS

|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 2020        | Model year 2020 <sup>[1]</sup><br>Assembly plant Lincoln, Alabama, United States                   |
| 6 Feb 2020  | Transport Canada recall 2020041 <sup>[2]</sup><br>Issued for the model year · Label                |
| 28 Jul 2020 | Transport Canada recall 2020346 <sup>[2]</sup><br>Issued for the model year · Visual system        |
| 28 Jul 2020 | Transport Canada recall 2020344 <sup>[2]</sup><br>Issued for the model year · Visual system        |
| 16 Mar 2023 | Transport Canada recall 2023136 <sup>[2]</sup><br>Issued for the model year · Visual system        |
| 15 Jun 2023 | Transport Canada recall 2023350 <sup>[2]</sup><br>Issued for the model year · Visual system        |
| 1 Feb 2024  | Transport Canada recall 2024059 <sup>[2]</sup><br>Issued for the model year · Airbag               |
| 13 Dec 2024 | Transport Canada recall 2024761 <sup>[2]</sup><br>Issued for the model year · Visual system        |
| 21 May 2026 | Transport Canada recall 2026251 <sup>[2]</sup><br>Issued for the model year · Seats and restraints |
| 4 Jun 2026  | Transport Canada recall 2026275 <sup>[2]</sup><br>Issued for the model year · Structure            |
| 26 Oct 2026 | Listed for sale, Dieppe, NB <sup>[5]</sup><br>Volkswagen Moncton · asking \$27,323                 |
| 29 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$27,323                                             |

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 14 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

