Register entry, as of 28 October 2026 Listed for sale Record ID b6ab7e94fed4

# 2023 Honda Pilot EX-L

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5FN | YG1H4 | 3 | P | B | 503643 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| American Honda Motor Co... | Pilot · 3.5 L | Verified | 2023 | Lincoln | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 3.5 L, 6 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Pilot | Drive | 4WD |
| Trim | EX-L | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Sport Utility Vehicle | Plant | Lincoln, Alabama, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/pilot/2023

**4** recalls listed by Transport Canada for this model year

### Brakes

2025318 12 Jun 2025

Issue: On certain vehicles, the brake pedal assembly may not have been manufactured properly. As a result, the brake pedal could move and cause you not to be able to apply the brakes properly, or to apply the brakes unexpectedly. This could also cause the brake lights to turn on without pressing the brake pedal. Safety Risk: Reduced braking and/or braking unexpectedly could increase the risk of a crash. Additionally, brake lights that turn on without the brake pedal being pressed could cause others not to recognize when the vehicle is braking or not braking and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the brake pedal assembly.

### Fuel system

2025029 23 Jan 2025

Issue: On certain vehicles, a software problem in the fuel injection electronic control unit could cause the engine to stall while driving. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the fuel injection electronic control unit software.

### Fuel system

2024725 27 Nov 2024

Issue: On certain vehicles, the fuel filler pipe may not have been connected properly to the filler neck. As a result, the connection could separate in a crash, and fuel could leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Honda will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, reposition the fuel filler pipe.

### Steering

2023593 2 Nov 2023

Issue: On certain vehicles, the steering gearbox may not have been manufactured correctly. As a result, the steering rack could lock up while driving. Safety Risk: A sudden loss of steering control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the steering gearbox.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $39,995[5], $7,248 under the median of $47,243[4].

| | |
|---|---|
| Lowest ask | $35,995 |
| Middle half | $44,545 – $49,655 |
| Median ask | $47,243 |
| This car | $39,995 |

Same model year · 46 live listings · as of 28 Oct 2026

OTHER 2023 HONDA PILOT LISTINGS [5]

| | |
|---|---|
| Halifax, NS · 167,791 km | $35,995 |
| Saint John, NB · 167,791 km | $35,995 |
| Grand Falls-Windsor, NL · 60,733 km | $47,995 |
| Clarenville, NL · 60,733 km | $47,995 |
| Truro, NS · 167,791 km | $35,995 |
| Truro, NS · 167,791 km | $35,995 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Lincoln, Alabama, United States |
| 2 Nov 2023 | Transport Canada recall 2023593[2]<br>Issued for the model year · Steering |
| 27 Nov 2024 | Transport Canada recall 2024725[2]<br>Issued for the model year · Fuel system |
| 23 Jan 2025 | Transport Canada recall 2025029[2]<br>Issued for the model year · Fuel system |
| 12 Jun 2025 | Transport Canada recall 2025318[2]<br>Issued for the model year · Brakes |
| 22 Feb 2026 | Listed for sale, Brooks, AB[5]<br>Honda Magic · asking $39,995 |

| | |
|---|---|
| 28 Oct 2026 | Listing last updated[5]<br>asking $39,995 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 46 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.