Register entry, as of 28 October 2026 Listed for sale Record ID cefec6124304

2025 Honda Pilot TRAILSPORT

3.5 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FN	YG1H6	8	S	B	502112
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
American Honda Motor Co...	Pilot · 3.5 L	Verified	2025	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Pilot	Drive	AWD
Trim	TRAILSPORT	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/pilot/2025

4 recalls listed by Transport Canada for this model year

Brakes

2025318 12 Jun 2025

Issue: On certain vehicles, the brake pedal assembly may not have been manufactured properly. As a result, the brake pedal could move and cause you not to be able to apply the brakes properly, or to apply the brakes unexpectedly. This could also cause the brake lights to turn on without pressing the brake pedal. Safety Risk: Reduced braking and/or braking unexpectedly could increase the risk of a crash. Additionally, brake lights that turn on without the brake pedal being pressed could cause others not to recognize when the vehicle is braking or not braking and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the brake pedal assembly.

Seats and restraints

2025049 5 Feb 2025

Issue: On certain vehicles, the third-row passenger-side seat belt may not have been routed correctly and could be trapped behind an interior panel. As a result, the seat belt can't be used. Safety Risk: Not wearing a seat belt can increase the risk of injury in a crash. Corrective Actions: To reduce the safety risk, Honda advises that if the seat belt can't be latched, you shouldn't transport a passenger in the third-row passenger-side seat until the recall repairs are completed. Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, correct the routing of the seat belt.

Fuel system

2025029 23 Jan 2025

Issue: On certain vehicles, a software problem in the fuel injection electronic control unit could cause the engine to stall while driving. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the fuel injection electronic control unit software.

Fuel system

2024725 27 Nov 2024

Issue: On certain vehicles, the fuel filler pipe may not have been connected properly to the filler neck. As a result, the connection could separate in a crash, and fuel could leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Honda will notify owners in writing and advise you to take your vehicle to a dealership to inspect and, if necessary, reposition the fuel filler pipe.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $55,247[5], $2,250 over the median of $52,997[4].

Lowest ask	$41,000
Middle half	$51,538 – $54,993
Median ask	$52,997
This car	$55,247

Same configuration · 22 live listings · as of 28 Oct 2026

OTHER 2025 HONDA PILOT LISTINGS [5]

Winnipeg, MB · 56,500 km	$53,999
Toronto, ON · 14,413 km	$53,995
Wetaskiwin, AB · 20,058 km	$57,550
Lower Sackville, NS · 30,100 km	$53,995
Woodbridge, ON · 6,281 km	$52,600
Brandon, MB · 80,737 km	$51,653

§4 EVENTS

2025	Model year 2025[1] Assembly plant Lincoln, Alabama, United States
27 Nov 2024	Transport Canada recall 2024725[2] Issued for the model year · Fuel system
23 Jan 2025	Transport Canada recall 2025029[2] Issued for the model year · Fuel system
5 Feb 2025	Transport Canada recall 2025049[2] Issued for the model year · Seats and restraints
12 Jun 2025	Transport Canada recall 2025318[2] Issued for the model year · Brakes
16 Sep 2026	Listed for sale, Lachine, QC[5] Spinelli Honda · asking $55,247

27 Oct 2026	Listing last updated[5] asking $55,247

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 22 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.