

Register entry, as of 28 October 2026

Listed for sale

Record ID 43d719d12532

2021 Honda Ridgeline SPORT

3.5 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FP **YK3F1** **7** **M** **B** **501903**

WMI 1-3

American Honda Motor Co...

DESCRIPTOR 4-8

Ridgeline · 3.5 L

CHECK 9

Verified

YEAR 10

2021

PLANT 11

United States

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Ridgeline	Drive	4WD
Trim	SPORT	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Pickup	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/ridgeline/2021

6 recalls listed by Transport Canada for this model year

Structure 2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

Seats and restraints 2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Visual system 2024265 9 May 2024

Issue: On certain vehicles, the tailgate wiring harness could become damaged. As a result, the rearview camera image may not display when the transmission is shifted into the reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the tailgate wiring harness.



Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Brakes

2023365 29 Jun 2023

Issue: On certain vehicles, the brake master cylinder could separate from the brake booster. If this happens, braking could be reduced or you could experience a complete loss of brakes. Safety Risk: Reduced braking or a loss of brakes can increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect the brake master cylinder and brake booster. The dealer will inspect for any missing nuts and damaged brake booster parts and replace them as necessary.

Visual system

2023136 16 Mar 2023

Issue: On certain vehicles, the side mirror glass may not be attached properly. As a result, the mirror glass could vibrate or fall off. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail. Due to a parts supply issue, Honda advises that you should only take your vehicle to a dealership if the mirror is loose, vibrating or has fully detached. Honda will send you a second notice when the replacement parts are available, and instruct you to take your vehicle to a dealership to replace the glass on both side mirrors.

Listed for the model year, not checked against your VIN. Honda confirms which apply.

Check your VIN with Honda Canada or call a Honda dealer with your VIN.

www.honda.ca/en/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$38,950^[5], \$1,460 over the median of \$37,490^[4].



Lowest ask	\$29,693
Middle half	\$34,500 – \$39,447
Median ask	\$37,490
This car	\$38,950

Same model year · 21 live listings · as of 28 Oct 2026

OTHER 2021 HONDA RIDGELINE LISTINGS ^[5]

Windsor, ON · 96,608 km	\$38,990
Winnipeg, MB · 83,579 km	\$41,197
Regina, SK · 83,579 km	\$41,197
Winnipeg, MB · 83,579 km	\$41,197
Lethbridge, AB · 42,833 km	\$43,927
Scarborough, ON · 97,002 km	\$34,890



§4 EVENTS

2021	Model year 2021 ^[1] Assembly plant United States
16 Mar 2023	Transport Canada recall 2023136 ^[2] Issued for the model year · Visual system
29 Jun 2023	Transport Canada recall 2023365 ^[2] Issued for the model year · Brakes
1 Feb 2024	Transport Canada recall 2024059 ^[2] Issued for the model year · Airbag
9 May 2024	Transport Canada recall 2024265 ^[2] Issued for the model year · Visual system
21 May 2026	Transport Canada recall 2026251 ^[2] Issued for the model year · Seats and restraints
4 Jun 2026	Transport Canada recall 2026275 ^[2] Issued for the model year · Structure
24 Oct 2026	Listed for sale, Georgetown, ON ^[5] Georgetown Kia · asking \$38,950
26 Oct 2026	Listing last updated ^[5] asking \$38,950

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 21 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

