

Register entry, as of 27 October 2026

Listed for sale

Record ID a5b0e51019ab

# 2016 Acura MDX SH-AWD w/Tech

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**5FR YD4H4 1 G B 506338**

WMI 1-3

Acura · AMERICAN HONDA...

DESCRIPTOR 4-8

MDX · 3.5 L

CHECK 9

Verified

YEAR 10

2016

PLANT 11

Lincoln

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                 |
|------------|-----------------------|--------|---------------------------------|
| Model year | 2016                  | Engine | 3.5 L, 6 cylinders              |
| Make       | Acura                 | Fuel   | Gasoline                        |
| Model      | MDX                   | Drive  | 4WD                             |
| Trim       | SH-AWD w/Tech         | Maker  | AMERICAN HONDA MOTOR CO., INC.  |
| Body       | Sport Utility Vehicle | Plant  | Lincoln, Alabama, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/acura/mdx/2016](https://cardog.app/tools/recalls/acura/mdx/2016)

## 3 recalls listed by Transport Canada for this model year

### Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

### Lights and instruments

2025212 17 Apr 2025

Issue: On certain vehicles, the recall repairs completed by a Honda or Acura dealer during recall AL65/AL66 (Transport Canada recall no. 2019-159) may not have been effective. As a result, a second repair is required. On certain vehicles, water could enter the tail lamps on the tailgate and cause a short circuit. As a result, the fuse could blow and cause a complete loss of rear lighting. Note: This recall replaces recall AL65/AL66 (Transport Canada recall no. 2019-159). Vehicles that previously had a fuse harness installed under that recall do not require this repair. Safety Risk: A loss of rear lighting could make the vehicle less visible and increase the risk of a crash. Corrective Actions: Acura will notify owners by mail and advise you to take your vehicle to a dealership to install a fuse harness. The dealer will also inspect and, if necessary, replace the tail lamps on the tailgate and repair the body dust sealer.

### Lights and instruments

2019159 28 Mar 2019

This recall was replaced by Transport Canada recall no. 2025-212. Issue: On certain vehicles, water could enter the tail lamps located on the tailgate. This could cause the tail lamps not to work properly. This could also cause a fuse to blow, which could result in a complete loss of rear lighting. Safety Risk: A loss of rear lighting could make the vehicle less visible and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to inspect the tailgate lid lamps. If either lamp is not working, the dealer will replace both lamps and inspect/replace the fuse. If both tailgate lid lamps are working, the dealer will modify the lamps, and install updated gaskets and wiring.




Listed for the model year, not checked against your VIN. Acura confirms which apply.  
Check your VIN with Acura Canada or call a Acura dealer with your VIN.  
[www.acura.ca/en/recalls](http://www.acura.ca/en/recalls)

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$15,995<sup>[5]</sup>, \$804 under the median of \$16,799<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$11,500            |
| Middle half | \$14,494 – \$20,495 |
| Median ask  | \$16,799            |
| This car    | \$15,995            |

Same configuration · 19 live listings · as of 27 Oct 2026

#### OTHER 2016 ACURA MDX LISTINGS <sup>[5]</sup>

|                           |          |
|---------------------------|----------|
| Laval, QC · 123,041 km    | \$15,995 |
| Québec, QC · 194,611 km   | \$11,995 |
| Red Deer, AB · 243,959 km | \$15,867 |
| Brossard, QC · 123,001 km | \$17,492 |
| Carignan, QC · 123,041 km | \$15,995 |
| Guelph, ON · 155,210 km   | \$16,995 |

### §4 EVENTS

|             |                                                                                                      |
|-------------|------------------------------------------------------------------------------------------------------|
| 2016        | Model year 2016 <sup>[1]</sup><br>Assembly plant Lincoln, Alabama, United States                     |
| 28 Mar 2019 | Transport Canada recall 2019159 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 17 Apr 2025 | Transport Canada recall 2025212 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 4 Jun 2026  | Transport Canada recall 2026275 <sup>[2]</sup><br>Issued for the model year · Structure              |
| 11 Jul 2026 | Listed for sale, Toronto, ON <sup>[5]</sup><br>Motorland Auto Sales Inc. · asking \$15,995           |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$15,995                                               |

### §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.



---

**SOURCES**

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 19 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                                  |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                     |

---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

