Register entry, as of 28 October 2026 Listed for sale Record ID 992ba346dc93

2014 Acura MDX SH-AWD Tech Ent

3.5 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5FR	YD4H6	8	E	B	504665
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Acura · AMERICAN HONDA…	MDX · 3.5 L	Verified	2014	Lincoln	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	MDX	Drive	Not in the decode
Trim	SH-AWD Tech Ent	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	Lincoln, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/mdx/2014

8 recalls listed by Transport Canada for this model year

Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

Lights and instruments

2025212 17 Apr 2025

Issue: On certain vehicles, the recall repairs completed by a Honda or Acura dealer during recall AL65/AL66 (Transport Canada recall no. 2019-159) may not have been effective. As a result, a second repair is required. On certain vehicles, water could enter the tail lamps on the tailgate and cause a short circuit. As a result, the fuse could blow and cause a complete loss of rear lighting. Note: This recall replaces recall AL65/AL66 (Transport Canada recall no. 2019-159). Vehicles that previously had a fuse harness installed under that recall do not require this repair. Safety Risk: A loss of rear lighting could make the vehicle less visible and increase the risk of a crash. Corrective Actions: Acura will notify owners by mail and advise you to take your vehicle to a dealership to install a fuse harness. The dealer will also inspect and, if necessary, replace the tail lamps on the tailgate and repair the body dust sealer.

Lights and instruments

2019159 28 Mar 2019

This recall was replaced by Transport Canada recall no. 2025-212. Issue: On certain vehicles, water could enter the tail lamps located on the tailgate. This could cause the tail lamps not to work properly. This could also cause a fuse to blow, which could result in a complete loss of rear lighting. Safety Risk: A loss of rear lighting could make the vehicle less visible and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to inspect the tailgate lid lamps. If either lamp is not working, the dealer will replace both lamps and inspect/replace the fuse. If both tailgate lid lamps are working, the dealer will modify the lamps, and install updated gaskets and wiring.

Engine

2015281 25 Jun 2015

On certain vehicles, some lots of A/C compressor clutch drive bolts may be defective. If the A/C clutch drive falls off the vehicle during operation while the vehicle is underway, the clutch drive could strike another vehicle, stationary object, or bystander, causing injury and/or property damage. Correction: Dealers will replace the clutch drive bolt, and if necessary install a new clutch plate.

Brakes

2015201 14 May 2015

On certain vehicles, the Collision Mitigation Braking System (CMBS) could unexpectedly activate while operating the vehicle. In rare cases, the system may interpret certain roadside objects, such as metal fences or metal guardrails, as obstacles and apply emergency braking through the CMBS. If the CMBS applies unexpected emergency braking force during normal operation, it could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle sofware for the system.

Seats and restraints

2014453 15 Oct 2014

On certain vehicles, in temperatures below minus 20° Celsius, the ability of the driver's and front passenger's seatbelt to extend and/or retract may be affected. This would result in a seatbelt that cannot be used properly or as it was intended, and could increase the potential for injury to the seat occupant(s) in a crash. Correction: Dealers will replace the driver's seatbelt and front passenger's seatbelt.

2 more on the model-year record, cardog.app/tools/recalls/acura/mdx/2014

> Listed for the model year, not checked against your VIN. Acura confirms which apply.
> Check your VIN with Acura Canada or call a Acura dealer with your VIN.
> www.acura.ca/en/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $15,495[5], $501 over the median of $14,994[4].

Lowest ask	$9,900
Middle half	$13,572 – $15,995
Median ask	$14,994
This car	$15,495

Same model year · 18 live listings · as of 28 Oct 2026

OTHER 2014 ACURA MDX LISTINGS [5]

Toronto, ON · 173,413 km	$9,900
Saskatoon, SK · 166,590 km	$15,995
Notre-Dame-des-Prairies, QC · 175,000 km	$12,500
Komoka, ON · 158,650 km	$13,995
Richmond, BC · 125,885 km	$16,499
Barrie, ON · 217,535 km	$12,990

§4 EVENTS

2014 Model year 2014[1]
Assembly plant Lincoln, Alabama, United States

22 Jul 2013	Transport Canada recall 2013250[2] Issued for the model year · Electrical
15 Nov 2013	Transport Canada recall 2013406[2] Issued for the model year · Powertrain
15 Oct 2014	Transport Canada recall 2014453[2] Issued for the model year · Seats and restraints
14 May 2015	Transport Canada recall 2015201[2] Issued for the model year · Brakes
25 Jun 2015	Transport Canada recall 2015281[2] Issued for the model year · Engine
28 Mar 2019	Transport Canada recall 2019159[2] Issued for the model year · Lights and instruments
17 Apr 2025	Transport Canada recall 2025212[2] Issued for the model year · Lights and instruments
4 Jun 2026	Transport Canada recall 2026275[2] Issued for the model year · Structure
25 Oct 2026	Listed for sale, Ottawa, ON[5] AZ Auto Sales and Services · asking $15,495
27 Oct 2026	Listing last updated[5] asking $15,495

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 18 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.