Register entry, as of 28 October 2026 Listed for sale Record ID b5fe0fd0ac35

2020 Buick Enclave Essence

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5GA	EVAKW	3	L	J	265137
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Buick · GENERAL MOTORS…	Enclave · 3.6 L	Verified	2020	Lansing - Delta Township	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	3.6 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	Enclave	Drive	AWD
Trim	Essence	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Lansing - Delta Township, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/enclave/2020

6 recalls listed by Transport Canada for this model year

Tires — 2021103 — 26 Feb 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.

Tires — 2020530 — 6 Nov 2020

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects vehicles equipped with certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the tires and replace the ones that have the DOT number and production mold number combinations identified by Continental.

Powertrain — 2020520 — 29 Oct 2020

Issue: On certain vehicles, the start-stop accumulator in the transmission may be missing bolts. As a result, transmission fluid could leak and eventually cause the transmission to stop working. If this happens, there could be a loss of power to the wheels. Safety Risk: A transmission fluid leak onto a hot surface can create the risk of a fire. Additionally, a loss of power to the wheels could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the transmission start-stop accumulator. It will be replaced if any bolts are found missing.

Fuel system

2020484 15 Oct 2020

Issue: On certain vehicles, there could be a problem with the fuel pump assembly. As a result, the flow of fuel to the engine could be partially blocked. Under certain conditions, like a low fuel level, this could cause the engine to stall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump module.

Airbag

2020350 30 Jul 2020

Issue: On certain vehicles, there may be a problem with the side curtain airbag inflators. As a result, the airbags may not inflate properly in a crash. Safety Risk: An airbag that does inflate properly could create an increased risk of injury in a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the side curtain airbags.

Structure

2019451 6 Sep 2019

Issue: On certain vehicles, the right-hand frame rail in the engine compartment may be cracked. This could cause reduced crash performance in certain frontal crashes. Safety Risk: Reduced crash performance could create an increased risk of injury. Corrective Actions: General Motors will notify owners by mail and instruct them to take their vehicle to a dealer for an inspection. If the frame rail is found cracked, the vehicle will be replaced.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,899[5], $5,089 under the median of $24,988[4].



Lowest ask	$19,899
Middle half	$20,749 – $30,316
Median ask	$24,988
This car	$19,899

Same model year · 6 live listings · as of 28 Oct 2026

OTHER 2020 BUICK ENCLAVE LISTINGS [5]

Sudbury, ON · 87,667 km	$29,995
Melfort, SK · 114,682 km	$34,900
Alliston, ON · 95,946 km	$26,977
Edmonton, AB · 143,371 km	$22,999
Hanover, ON · 150,121 km	$19,999
Roblin, MB · 142,101 km	$31,429

§4 EVENTS

2020	Model year 2020[1] Assembly plant Lansing - Delta Township, Michigan, United States
6 Sep 2019	Transport Canada recall 2019451[2] Issued for the model year · Structure

30 Jul 2020	Transport Canada recall 2020350[2] Issued for the model year · Airbag
15 Oct 2020	Transport Canada recall 2020484[2] Issued for the model year · Fuel system
29 Oct 2020	Transport Canada recall 2020520[2] Issued for the model year · Powertrain
6 Nov 2020	Transport Canada recall 2020530[2] Issued for the model year · Tires
26 Feb 2021	Transport Canada recall 2021103[2] Issued for the model year · Tires
25 Oct 2026	Listed for sale, Winnipeg, MB[5] Platinum Auto Sales Inc. · asking $19,899
27 Oct 2026	Listing last updated[5] asking $19,899

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 6 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.