Register entry, as of 26 October 2026 Listed for sale Record ID 84b3d74969ac

2014 Buick Enclave Leather

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5GA	KVBKD	2	E	J	222225
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Buick · GENERAL MOTORS…	Enclave · 3.6 L	Verified	2014	Lansing	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.6 L, 6 cylinders
Make	Buick	Fuel	Gasoline
Model	Enclave	Drive	AWD
Trim	Leather	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Lansing, Michigan, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/enclave/2014

5 recalls listed by Transport Canada for this model year

Airbag

2023277 10 May 2023

Issue: On certain vehicles, the driver-front airbag inflator could rupture when the airbag deploys in a crash. If this happens, the airbag may not properly inflate and fragments could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury or death. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag module.

Airbag

2021213 8 Apr 2021

Issue: On a small number of vehicles, the right or left roof rail airbag may not be properly attached to the vehicle. As a result, the airbags may not work properly in a crash. Safety Risk: An airbag that does not work properly could create an increased risk of injury in a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the roof rail airbag attachments. The dealer will add or replace any attachments that are missing, damaged or out of position.

Electrical

2014432 3 Oct 2014

On certain vehicles, the chassis electronic module may have been contaminated at time of manufacture, which could cause an electrical short to occur within the module. This could cause the vehicle's check engine light to be displayed, or cause the engine to fail to start or stall, resulting in a loss of motive power. If the vehicle is equipped to support electric trailer brakes, the vehicle could also lose trailer brake function and display a "Service Trailer Brake System" indicator. These issues could increase the risk of a crash resulting in injury and/or damage to property. Correction: Dealers will replace the module with a revised part.

Seats and restraints

2014181 21 May 2014

On certain vehicles, the flexible steel cable that connects the seat belt to the vehicle structure at the front outboard seating positions can fatigue over time and could separate, increasing the risk of injury in a crash. Correction: Dealers will inspect and repair or replace the lap pretensioner, as necessary.

Lights and instruments

2014165 7 May 2014

On certain vehicles, the fuel gauge may indicate a greater quantity of fuel than what remains in the tank. As a result, if the tank were to become empty, the engine could stall, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will recalibrate the engine control module.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,995[5], the median[4].



Lowest ask	$9,900
Middle half	$9,995 – $12,900
Median ask	$10,995
This car	$10,995

Same model year · 5 live listings · as of 26 Oct 2026

OTHER 2014 BUICK ENCLAVE LISTINGS [5]

Watrous, SK · 146,627 km	$22,995
Wadena, SK · 216,182 km	$9,900
Vegreville, AB · 234,317 km	$9,995
Smoky Lake, AB · 234,317 km	$9,995
Williams Lake, BC · 181,500 km	$12,900

§4 EVENTS

2014	Model year 2014[1] Assembly plant Lansing, Michigan, United States
7 May 2014	Transport Canada recall 2014165[2] Issued for the model year · Lights and instruments
21 May 2014	Transport Canada recall 2014181[2] Issued for the model year · Seats and restraints
3 Oct 2014	Transport Canada recall 2014432[2] Issued for the model year · Electrical

8 Apr 2021	Transport Canada recall 2021213[2] Issued for the model year · Airbag
10 May 2023	Transport Canada recall 2023277[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Meadow Lake, SK[5] Eagle Creek GM · asking $10,995

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 5 live listings, as of 26 Oct 2026

[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.