Register entry, as of 26 October 2026 Listed for sale Record ID 86d75fd11333

2008 Hummer H2

6.2 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5GR	GN238	5	8	H	106839
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Hummer · GENERAL MOTO…	H2 · 6.2 L	Verified	2008	Mishawaka	Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	6.2 L, 8 cylinders
Make	Hummer	Fuel	Gasoline
Model	H2	Drive	4WD
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Mishawaka, Indiana, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hummer/h2/2008

3 recalls listed by Transport Canada for this model year

Accessories

2010189 7 Jun 2010

On certain vehicles equipped with a Heated Washer Fluid System (HWFS), a short circuit on the printed circuit board for the washer fluid heater may overheat the control-circuit ground wire. A repair was implemented in a recall in 2008, however, there have been new reports of thermal incidents on heated washer fluid system modules after this improvement was installed. This situation may cause some minor distortion, but also could lead to melting of the plastic around the heated washer fluid system, or cause a fire. Correction: Dealers will permanently disable and remove the heated washer fluid module. An updated page will be provided and inserted in the Owner Manual to document the removal of the feature.

Other

2008313 29 Aug 2008

On certain vehicles equipped with a heated washer fluid system, a short circuit on the printed circuit board for the washer fluid heater may overheat the control-circuit ground wire. This situation may cause other electrical features to malfunction which could cause smoke and in some cases a fire. Correction: Dealer will install a wire harness with an in-line fuse.

Brakes

2007271 23 Aug 2007

On certain vehicles the ABS wheel speed sensor wiring harnesses may be reversed, which may result in vehicle instability and extended stopping distances under certain circumstances. Correction: Dealers will correct the wheel speed sensor wiring and reprogram the brake control module.

Listed for the model year, not checked against your VIN. Hummer confirms which apply.
Check your VIN with GM Canada or call a Hummer dealer with your VIN.
experience.gm.ca/en/ownercenter/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

Median ask $67,388[4] for same model year.

Lowest ask	$27,500
Middle half	$55,541 – $74,360
Median ask	$67,388
This car	US$64,888

Same model year · 4 live listings · as of 26 Oct 2026

OTHER 2008 HUMMER H2 LISTINGS [5]

Edmonton, AB · 286,682 km	$27,500
Edmonton, AB · 286,682 km	$27,500
Scarborough, ON · 0 km	$87,777

§4 EVENTS

2008	Model year 2008[1] Assembly plant Mishawaka, Indiana, United States
23 Aug 2007	Transport Canada recall 2007271[2] Issued for the model year · Brakes
29 Aug 2008	Transport Canada recall 2008313[2] Issued for the model year · Other
7 Jun 2010	Transport Canada recall 2010189[2] Issued for the model year · Accessories
25 Oct 2026	Listed for sale, Sylvan Lake, AB[5] Adrenalin Motors · asking US$64,888
26 Oct 2026	Listing last updated[5] asking US$64,888

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 4 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.