

Register entry, as of 28 October 2026

Listed for sale

Record ID 3552a72023e6

2005 Hummer H2

6.0 L, 8 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5GR **GN23U** **5** **5** **6** **H12231**

WMI 1-3

Hummer · GENERAL MOTO...

DESCRIPTOR 4-8

H2 · 6.0 L

CHECK 9

Verified

YEAR 10

2005

PLANT 11

Oklahoma City

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2005	Engine	6.0 L, 8 cylinders
Make	Hummer	Fuel	Gasoline
Model	H2	Drive	4WD
Trim	Not in the decode	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Oklahoma City, Oklahoma, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/hummer/h2/2005

2 recalls listed by Transport Canada for this model year

Seats and restraints 2005119 25 Apr 2005

On certain vehicles, the 2nd row centre occupant seat belt routing may make it difficult to position the lap portion of the safety belt low around the hips of occupants. A lap portion of the seat belt routing that is not low and snug on the hips can allow unfavourable occupant kinetics in the event of a crash. Moreover, the higher routing allows the lap belt to ride up on an occupant's abdomen instead of fitting low around their hipbones, and therefore, can expose them to more risk of abdominal and internal organ injury. Correction: Dealers will modify the guide loop.

Brakes 2005033 15 Feb 2005

On certain vehicles, the hydraulic brake booster's pressure accumulator may crack and/or separate from the Hydro-Boost assembly during normal vehicle operating conditions. If a separation occurred and the hood of the vehicle was open, fragments from the accumulator could cause injury to people in the immediate area. In addition, the presence of this crack or fractured surface could allow the hydraulic fluid to leak from the accumulator circuit of the booster assembly. The loss of fluid would cause increased steering and braking effort. Correction: Dealers will test and, if necessary, replace the Hydro-Boost assembly.

Listed for the model year, not checked against your VIN. Hummer confirms which apply.

Check your VIN with GM Canada or call a Hummer dealer with your VIN.

experience.gm.ca/en/ownercenter/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$16,975^[5], \$5,024 under the median of \$21,999^[4].



Lowest ask	\$16,975
Middle half	\$19,487 – \$33,499
Median ask	\$21,999
This car	\$16,975

Same model year · 3 live listings · as of 28 Oct 2026

OTHER 2005 HUMMER H2 LISTINGS [5]

Red Deer, AB · 0 km	US\$44,999
Mississauga, ON · 197,599 km	\$21,999

§4 EVENTS

2005	Model year 2005 ^[1] Assembly plant Oklahoma City, Oklahoma, United States
15 Feb 2005	Transport Canada recall 2005033 ^[2] Issued for the model year · Brakes
25 Apr 2005	Transport Canada recall 2005119 ^[2] Issued for the model year · Seats and restraints
28 Feb 2025	Listed for sale, Lacombe, AB ^[5] Empire Auto Sales · asking \$16,975
28 Oct 2026	Listing last updated ^[5] asking \$16,975

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 3 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

