Register entry, as of 26 November 2026 Listed for sale Record ID 056154b3b268

# 2007 Honda CR-V EX-L

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 5J6 | RE487 | 6 | 7 | L | 813220 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| American Honda Motor Co... | CR-V · 2.4 L | Verified | 2007 | East Liberty | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2007 | Engine | 2.4 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | CR-V | Drive | 4WD |
| Trim | EX-L | Maker | AMERICAN HONDA MOTOR CO., INC. |
| Body | Sport Utility Vehicle | Plant | East Liberty, Ohio, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/cr-v/2007

7 recalls listed by Transport Canada for this model year

### Structure

2023187 30 Mar 2023

Issue: On certain vehicles, the rear frame could rust. In extreme cases, this could result in a rear trailing arm separating from the vehicle. Note: This recall replaces recall HN70 (Transport Canada Recall No. 2019-025). Vehicles that were inspected or repaired under that recall also require this second inspection and repair. Safety Risk: A rear trailing arm that separates could cause a loss of control and increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership for an inspection of the rear frame stiffeners. If the vehicle passes the inspection, the dealer will install a brace. For a vehicle that does not pass the inspection, Honda will repurchase the vehicle. In the event the repurchase is declined by an owner, a secondary inspection and body shop repair method may be possible.

### Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

### Structure

2019025 17 Jan 2019

This recall was replaced by Transport Canada Recall No. 2023-187. Issue: On certain vehicles, the rear frame could rust. In extreme cases, this could result in a rear trailing arm separating from the vehicle. This recall applies to vehicles originally sold or currently registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A rear trailing arm that separates could cause a loss of control and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection of the rear frame stiffeners. If the vehicle passes the inspection, dealers will apply corrosion protection. For a vehicle that does not pass the inspection, Honda will repurchase the vehicle. In the event the repurchase is declined by an owner, a secondary inspection and body shop repair method may be possible.

### Airbag

2017326 30 Jun 2017

Certain vehicles may have received an incorrect wiring harness for the passenger frontal airbag inflator during a previous recall repair (Transport Canada recall 2017-009). This could affect the proper function of the passenger frontal airbag, which could increase the risk of injury to the front passenger occupant. Correction: Dealers will inspect the passenger frontal airbag inflator to see if the correct wire harness was installed and, if necessary, replace the inflator and the wire harness with new parts.

### Airbag

2017009 10 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag inflator. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

### Airbag

2016046 1 Feb 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect/replace the driver's frontal airbag inflator. Note: Honda Canada has created a special Airbag Inflator Hotline for immediate assistance. For more information, please contact: For Honda Owners: 1-877-445-7754 For Acura Owners: 1-877-445-9844

1 more on the model-year record, cardog.app/tools/recalls/honda/cr-v/2007

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $7,495[5], $1,905 under the median of $9,400[4].




| | |
|---|---|
| Lowest ask | $4,900 |
| Middle half | $7,495 – $10,988 |
| Median ask | $9,400 |
| This car | $7,495 |

Same model year · 5 live listings · as of 25 Nov 2026

### OTHER 2007 HONDA CR-V LISTINGS [5]

| | |
|---|---|
| Edmonton, AB · 225,122 km | $10,988 |
| Langley, BC · 230,625 km | $9,400 |
| Port Moody, BC · 455,290 km | $4,900 |
| London, ON · 145,950 km | $11,995 |

## §4 EVENTS

| | |
|---|---|
| 2007 | Model year 2007[1]<br>Assembly plant East Liberty, Ohio, United States |
| 5 Aug 2011 | Transport Canada recall 2011286[2]<br>Issued for the model year · Powertrain |
| 1 Feb 2016 | Transport Canada recall 2016046[2]<br>Issued for the model year · Airbag |
| 10 Jan 2017 | Transport Canada recall 2017009[2]<br>Issued for the model year · Airbag |
| 30 Jun 2017 | Transport Canada recall 2017326[2]<br>Issued for the model year · Airbag |
| 17 Jan 2019 | Transport Canada recall 2019025[2]<br>Issued for the model year · Structure |
| 21 Aug 2019 | Transport Canada recall 2019420[2]<br>Issued for the model year · Other |
| 30 Mar 2023 | Transport Canada recall 2023187[2]<br>Issued for the model year · Structure |
| 16 Dec 2025 | Listed for sale, Abbotsford, BC[5]<br>Eminence Auto Works · asking $7,495 |
| 26 Nov 2026 | Listing last updated[5]<br>asking $7,495 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 5 live listings, as of 25 Nov 2026
[5] Live public dealer listings on Cardog, as of 26 Nov 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.