

Register entry, as of 29 October 2026

Listed for sale

Record ID 19cbe69772fe

2017 Acura RDX Tech Package/Tech with Acura Watch Plus Package

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**5J8** **TB4H5** **3** **H** **L** **801662**

WMI 1-3

Acura · AMERICAN HONDA...

DESCRIPTOR 4-8

RDX · 3.5 L

CHECK 9

Verified

YEAR 10

2017

PLANT 11

East Liberty

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	RDX	Drive	4WD
Trim	Tech Package/Tech with Acura Watch Plus Package	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	East Liberty, Ohio, United States

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/acura/rdx/2017

1 recall listed by Transport Canada for this model year

Airbag

2019323 28 Jun 2019


Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Note: This is a new recall campaign that includes vehicles that had an airbag inflator replaced under a previous recall or had a replacement airbag installed. The previous recall provided an interim (short-term) repair. Interim repair parts must be replaced with the final repair parts provided in this recall. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to replace the driver and/or passenger-front airbag inflator. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Listed for the model year, not checked against your VIN. Acura confirms which apply.
Check your VIN with Acura Canada or call a Acura dealer with your VIN.

www.acura.ca/en/recallsUnited States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$15,499^[5], \$1,500 under the median of \$16,999^[4].



Lowest ask	\$11,495
Middle half	\$15,499 – \$18,495
Median ask	\$16,999
This car	\$15,499

Same configuration · 25 live listings · as of 29 Oct 2026

OTHER 2017 ACURA RDX LISTINGS [5]

Lévis, QC · 136,911 km	\$16,995
Vancouver, BC · 195,984 km	\$17,995
Victoriaville, QC · 173,654 km	\$16,995
Newmarket, ON · 140,371 km	\$18,788
Mcmastrerville, QC · 212,740 km	\$11,495
Vancouver, BC · 195,984 km	\$17,995

§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant East Liberty, Ohio, United States
28 Jun 2019	Transport Canada recall 2019323 ^[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Drummondville, QC ^[5] Drummondville Ford · asking \$15,499
29 Oct 2026	Listing last updated ^[5] asking \$15,499

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same configuration, 25 live listings, as of 29 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 29 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

