Register entry, as of 27 October 2026 Listed for sale Record ID 57acdcfe23a0

2018 Acura RDX Tech Package/Tech with Acura Watch Plus Package

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5J8	TB4H5	3	J	L	800176
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Acura · AMERICAN HONDA…	RDX · 3.5 L	Verified	2018	East Liberty	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	RDX	Drive	4WD
Trim	Tech Package/Tech with Acura Watch Plus Package	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	East Liberty, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/rdx/2018

2 recalls listed by Transport Canada for this model year

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Listed for the model year, not checked against your VIN. Acura confirms which apply.
Check your VIN with Acura Canada or call a Acura dealer with your VIN.
www.acura.ca/en/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $15,995[5], $4,980 under the median of $20,975[4].

Lowest ask	$15,480
Middle half	$18,995 – $22,242
Median ask	$20,975
This car	$15,995

Same configuration · 11 live listings · as of 27 Oct 2026

OTHER 2018 ACURA RDX LISTINGS [5]

Pointe-Aux-Trembles, QC · 159,397 km	$15,480
St. Catharines, ON · 142,136 km	$19,997
New Glasgow, NS · 225,919 km	$17,895
Barrie, ON · 135,478 km	$22,595
Maple Ridge, BC · 110,000 km	$20,138
Toronto, ON · 87,839 km	$23,995

§4 EVENTS

2018	Model year 2018[1] Assembly plant East Liberty, Ohio, United States
18 Dec 2023	Transport Canada recall 2023679[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262[2] Issued for the model year · Fuel system
24 Oct 2026	Listed for sale, Toronto, ON[5] Stallion Auto Sales · asking $15,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 11 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.