

Register entry, as of 29 October 2026

Listed for sale

Record ID 179cf2318b64

2013 Acura RDX Technology Package

3.5 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**5J8 TB4H5 5 D L 804217**

WMI 1-3

Acura · AMERICAN HONDA...

DESCRIPTOR 4-8

RDX · 3.5 L

CHECK 9

Verified

YEAR 10

2013

PLANT 11

East Liberty

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2013	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	RDX	Drive	AWD
Trim	Technology Package	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	East Liberty, Ohio, United States

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/acura/rdx/2013

2 recalls listed by Transport Canada for this model year

Airbag

2016046 1 Feb 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect/replace the driver's frontal airbag inflator. Note: Honda Canada has created a special Airbag Inflator Hotline for immediate assistance. For more information, please contact: For Honda Owners: 1-877-445-7754 For Acura Owners: 1-877-445-9844

Other

2013114 10 Apr 2013

On certain vehicles, the brake-shift interlock may not function properly at low temperatures. This could allow the transmission gear shift lever to be moved out of the PARK position without depressing the brake pedal. Depending which gear the driver selects, the vehicle could begin to move forward or backward immediately. This movement could result in property damage, or cause the vehicle to strike a bystander, potentially resulting in personal injury. Correction: Dealers will replace the gear shift assembly stopper.

Listed for the model year, not checked against your VIN. Acura confirms which apply.

Check your VIN with Acura Canada or call a Acura dealer with your VIN.

www.acura.ca/en/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$13,995^[5], \$1,500 over the median of \$12,495^[4].



Lowest ask	\$7,500
Middle half	\$11,000 – \$12,997
Median ask	\$12,495
This car	\$13,995

Same model year · 9 live listings · as of 29 Oct 2026

OTHER 2013 ACURA RDX LISTINGS [5]

Toronto, ON · 184,423 km	\$7,500
Laval, QC · 207,036 km	\$8,495
Montréal Nord, QC · 98,595 km	\$12,997
Toronto, ON · 157,810 km	\$12,495
Cambridge, ON · 161,000 km	\$11,999
Richmond, BC · 158,167 km	\$12,995

§4 EVENTS

2013	Model year 2013 ^[1] Assembly plant East Liberty, Ohio, United States
10 Apr 2013	Transport Canada recall 2013114 ^[2] Issued for the model year · Other
1 Feb 2016	Transport Canada recall 2016046 ^[2] Issued for the model year · Airbag
16 Dec 2025	Listed for sale, Abbotsford, BC ^[5] Eminence Auto Works · asking \$13,995
28 Oct 2026	Listing last updated ^[5] asking \$13,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 9 live listings, as of 29 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 29 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

