

Register entry, as of 29 October 2026

Listed for sale

Record ID 2370e44c0cd3

# 2017 Acura RDX Tech Package/Tech with Acura Watch Plus Package

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER <sup>[1]</sup>**5J8 TB4H5 6 H L 805091**

WMI 1-3

Acura · AMERICAN HONDA...

DESCRIPTOR 4-8

RDX · 3.5 L

CHECK 9

Verified

YEAR 10

2017

PLANT 11

East Liberty

SERIAL 12-17

Build sequence

## §1 IDENTITY <sup>[1]</sup>

|            |                                                 |        |                                   |
|------------|-------------------------------------------------|--------|-----------------------------------|
| Model year | 2017                                            | Engine | 3.5 L, 6 cylinders                |
| Make       | Acura                                           | Fuel   | Gasoline                          |
| Model      | RDX                                             | Drive  | 4WD                               |
| Trim       | Tech Package/Tech with Acura Watch Plus Package | Maker  | AMERICAN HONDA MOTOR CO., INC.    |
| Body       | Sport Utility Vehicle                           | Plant  | East Liberty, Ohio, United States |

## §2 OBLIGATIONS <sup>[2]</sup>

cardog.app/tools/recalls/acura/rdx/2017

### 1 recall listed by Transport Canada for this model year

#### Airbag

2019323 28 Jun 2019


Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Note: This is a new recall campaign that includes vehicles that had an airbag inflator replaced under a previous recall or had a replacement airbag installed. The previous recall provided an interim (short-term) repair. Interim repair parts must be replaced with the final repair parts provided in this recall. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to replace the driver and/or passenger-front airbag inflator. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Listed for the model year, not checked against your VIN. Acura confirms which apply.  
Check your VIN with Acura Canada or call a Acura dealer with your VIN.

[www.acura.ca/en/recalls](http://www.acura.ca/en/recalls)United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$20,210<sup>[5]</sup>, \$3,211 over the median of \$16,999<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$11,495            |
| Middle half | \$15,499 – \$18,495 |
| Median ask  | \$16,999            |
| This car    | \$20,210            |

Same configuration · 25 live listings · as of 29 Oct 2026

## OTHER 2017 ACURA RDX LISTINGS [5]

|                                |          |
|--------------------------------|----------|
| Lévis, QC · 136,911 km         | \$16,995 |
| Vancouver, BC · 195,984 km     | \$17,995 |
| Victoriaville, QC · 173,654 km | \$16,995 |
| Newmarket, ON · 140,371 km     | \$18,788 |
| Mcmastrville, QC · 212,740 km  | \$11,495 |
| Vancouver, BC · 195,984 km     | \$17,995 |

## §4 EVENTS

|             |                                                                                        |
|-------------|----------------------------------------------------------------------------------------|
| 2017        | Model year 2017 <sup>[1]</sup><br>Assembly plant East Liberty, Ohio, United States     |
| 28 Jun 2019 | Transport Canada recall 2019323 <sup>[2]</sup><br>Issued for the model year · Airbag   |
| 1 Oct 2026  | Listed for sale, Laval, QC <sup>[5]</sup><br>Lexus Laval (Sub-Prime) · asking \$20,210 |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$20,210                                 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

|                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 25 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

