

Register entry, as of 28 October 2026

Listed for sale

Record ID acff9d6c42b

# 2019 Acura RDX SH-AWD A-SPEC

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**5J8 TC2H6 2 K L 803985**

WMI 1-3

Acura · AMERICAN HONDA...

DESCRIPTOR 4-8

RDX · 2.0 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

East Liberty

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                                   |
|------------|-----------------------|--------|-----------------------------------|
| Model year | 2019                  | Engine | 2.0 L, 4 cylinders                |
| Make       | Acura                 | Fuel   | Gasoline                          |
| Model      | RDX                   | Drive  | 4WD                               |
| Trim       | SH-AWD A-SPEC         | Maker  | AMERICAN HONDA MOTOR CO., INC.    |
| Body       | Sport Utility Vehicle | Plant  | East Liberty, Ohio, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/acura/rdx/2019](https://cardog.app/tools/recalls/acura/rdx/2019)

## 5 recalls listed by Transport Canada for this model year

### Fuel system 2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

### Fuel system 2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

### Seats and restraints 2023127 9 Mar 2023

Issue: On certain vehicles, the seat belt buckles for the driver and front-passenger seats could wear over time and may not latch securely. If this happens, the seat belt could unlatch unexpectedly. Safety Risk: A seat belt that doesn't latch securely could create an increased risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the driver and front-passenger seat belt assemblies. In most cases, the seat belt buckle release buttons will be replaced. If the dealer determines that a buckle can't be repaired, it will be replaced with a new part.



## Fuel system

2021182 26 Mar 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada Recall No. 2020-236. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

## Fuel system

2020236 28 May 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: For the RLX model, only the RLX Hybrid model is affected by this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

Listed for the model year, not checked against your VIN. Acura confirms which apply.


Check your VIN with Acura Canada or call a Acura dealer with your VIN.

[www.acura.ca/en/recalls](http://www.acura.ca/en/recalls)

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

## §3 VALUE [4]

This car asks \$32,729<sup>[5]</sup>, \$6,892 over the median of \$25,837<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$16,990            |
| Middle half | \$23,189 – \$28,772 |
| Median ask  | \$25,837            |
| This car    | \$32,729            |

Same configuration · 19 live listings · as of 28 Oct 2026

## OTHER 2019 ACURA RDX LISTINGS [5]

|                             |          |
|-----------------------------|----------|
| Lethbridge, AB · 103,217 km | \$32,995 |
| Kitchener, ON · 110,424 km  | \$31,697 |
| Halifax, NS · 87,887 km     | \$26,449 |
| Truro, NS · 87,887 km       | \$26,449 |
| Saint John, NB · 87,887 km  | \$26,449 |
| Antigonish, NS · 87,887 km  | \$26,449 |

## §4 EVENTS

|             |                                                                                           |
|-------------|-------------------------------------------------------------------------------------------|
| 2019        | Model year 2019 <sup>[1]</sup><br>Assembly plant East Liberty, Ohio, United States        |
| 28 May 2020 | Transport Canada recall 2020236 <sup>[2]</sup><br>Issued for the model year · Fuel system |
| 26 Mar 2021 | Transport Canada recall 2021182 <sup>[2]</sup><br>Issued for the model year · Fuel system |



|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 9 Mar 2023  | Transport Canada recall 2023127 <sup>[2]</sup><br>Issued for the model year · Seats and restraints |
| 18 Dec 2023 | Transport Canada recall 2023679 <sup>[2]</sup><br>Issued for the model year · Fuel system          |
| 6 May 2024  | Transport Canada recall 2024262 <sup>[2]</sup><br>Issued for the model year · Fuel system          |
| 23 Apr 2026 | Listed for sale, Vernon, BC <sup>[5]</sup><br>Vernon Hyundai · asking \$32,729                     |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$32,729                                             |

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 19 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

