Register entry, as of 29 October 2026 Listed for sale Record ID 46fbe0f8d011

2021 Acura RDX SH-AWD A-SPEC

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5J8	TC2H6	5	M	L	808598
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Acura · AMERICAN HONDA…	RDX · 2.0 L	Verified	2021	East Liberty	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Acura	Fuel	Gasoline
Model	RDX	Drive	4WD
Trim	SH-AWD A-SPEC	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	East Liberty, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/rdx/2021

3 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Powertrain

2021731 3 Dec 2021

Issue: On certain vehicles, the left-front axle shaft was not properly heat-treated. As a result, the axle shaft could fail and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Acura will notify owners by mail and instruct you to take your vehicle to a dealer to replace the left-front axle shaft.

> Listed for the model year, not checked against your VIN. Acura confirms which apply.
> Check your VIN with Acura Canada or call a Acura dealer with your VIN.
> www.acura.ca/en/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $34,995[5], $107 over the median of $34,888[4].

Lowest ask	$27,990
Middle half	$31,921 – $36,600
Median ask	$34,888
This car	$34,995

Same configuration · 31 live listings · as of 29 Oct 2026

OTHER 2021 ACURA RDX LISTINGS [5]

Grande Prairie, AB · 44,369 km	$36,999
Shawinigan, QC · 135,570 km	$29,588
Lethbridge, AB · 76,631 km	$38,227
Thornhill, ON · 61,168 km	$30,588
Steinbach, MB · 150,718 km	$29,995
Saint-Hyacinthe, QC · 113,020 km	$24,995

§4 EVENTS

2021	Model year 2021[1] Assembly plant East Liberty, Ohio, United States
3 Dec 2021	Transport Canada recall 2021731[2] Issued for the model year · Powertrain
1 Feb 2024	Transport Canada recall 2024059[2] Issued for the model year · Airbag
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Woodbridge, ON[5] MARANELLO BMW · asking $34,995
28 Oct 2026	Listing last updated[5] asking $34,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 31 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.