

Register entry, as of 27 October 2026

Listed for sale

Record ID ca11683bd1a0

2020 Acura RDX Super Handling AWD A-SPEC

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5J8 TC2H6 9 L L 808473

WMI 1-3

Acura · AMERICAN HONDA...

DESCRIPTOR 4-8

RDX · 2.0 L

CHECK 9

Verified

YEAR 10

2020

PLANT 11

East Liberty

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Acura	Fuel	Gasoline
Model	RDX	Drive	4WD
Trim	Super Handling AWD A-SPEC	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	East Liberty, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/rdx/2020

5 recalls listed by Transport Canada for this model year

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.



Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Seats and restraints

2023127 9 Mar 2023

Issue: On certain vehicles, the seat belt buckles for the driver and front-passenger seats could wear over time and may not latch securely. If this happens, the seat belt could unlatch unexpectedly. Safety Risk: A seat belt that doesn't latch securely could create an increased risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the driver and front-passenger seat belt assemblies. In most cases, the seat belt buckle release buttons will be replaced. If the dealer determines that a buckle can't be repaired, it will be replaced with a new part.

Fuel system

2021182 26 Mar 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada Recall No. 2020-236. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

Listed for the model year, not checked against your VIN. Acura confirms which apply.

Check your VIN with Acura Canada or call a Acura dealer with your VIN.

www.acura.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$31,995^[5], \$3,500 over the median of \$28,495^[4].



Lowest ask	\$18,495
Middle half	\$26,045 – \$31,992
Median ask	\$28,495
This car	\$31,995

Same configuration · 22 live listings · as of 27 Oct 2026

OTHER 2020 ACURA RDX LISTINGS ^[5]

Calgary, AB · 162,062 km	\$25,900
Moncton, NB · 160,810 km	\$26,194
Smiths Falls, ON · 48,331 km	\$36,892
Toronto, ON · 62,165 km	\$31,995
Oakville, ON · 150,710 km	\$22,988
Kamloops, BC · 178,468 km	\$28,998

§4 EVENTS

2020

Model year 2020^[1]

Assembly plant East Liberty, Ohio, United States



26 Mar 2021	Transport Canada recall 2021182 ^[2] Issued for the model year · Fuel system
9 Mar 2023	Transport Canada recall 2023127 ^[2] Issued for the model year · Seats and restraints
18 Dec 2023	Transport Canada recall 2023679 ^[2] Issued for the model year · Fuel system
1 Feb 2024	Transport Canada recall 2024059 ^[2] Issued for the model year · Airbag
6 May 2024	Transport Canada recall 2024262 ^[2] Issued for the model year · Fuel system
22 Oct 2026	Listed for sale, Lower Sackville, NS ^[5] Top Shelf Auto Sales · asking \$31,995
27 Oct 2026	Listing last updated ^[5] asking \$31,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 22 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

