Register entry, as of 27 October 2026 Listed for sale Record ID fed6ac770039

2019 Acura MDX Tech

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5J8	YD4H4	X	K	L	805285
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Acura · AMERICAN HONDA…	MDX · 3.5 L	Verified	2019	East Liberty	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.5 L, 6 cylinders
Make	Acura	Fuel	Gasoline
Model	MDX	Drive	4WD
Trim	Tech	Maker	AMERICAN HONDA MOTOR CO., INC.
Body	Sport Utility Vehicle	Plant	East Liberty, Ohio, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/acura/mdx/2019

10 recalls listed by Transport Canada for this model year

Structure

2026275 4 Jun 2026

Issue: On certain vehicles, the suspension mounting points on the rear subframe could rust. As a result, rear suspension components could fail. This could lead to poor handling and a loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and install a rear subframe reinforcement kit or replace the subframe, as necessary.

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Lights and instruments

2025212 17 Apr 2025

Issue: On certain vehicles, the recall repairs completed by a Honda or Acura dealer during recall AL65/AL66 (Transport Canada recall no. 2019-159) may not have been effective. As a result, a second repair is required. On certain vehicles, water could enter the tail lamps on the tailgate and cause a short circuit. As a result, the fuse could blow and cause a complete loss of rear lighting. Note: This recall replaces recall AL65/AL66 (Transport Canada recall no. 2019-159). Vehicles that previously had a fuse harness installed under that recall do not require this repair. Safety Risk: A loss of rear lighting could make the vehicle less visible and increase the risk of a crash. Corrective Actions: Acura will notify owners by mail and advise you to take your vehicle to a dealership to install a fuse harness. The dealer will also inspect and, if necessary, replace the tail lamps on the tailgate and repair the body dust sealer.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Engine

2023603 8 Nov 2023

Issue: On certain vehicles equipped with a V6 engine, the connecting rod bearings could wear prematurely and become damaged. If this happens, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Safety Risk: An engine failure could cause a sudden loss of power and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect the engine. If damage is found, the dealer will replace the necessary parts.

4 more on the model-year record, cardog.app/tools/recalls/acura/mdx/2019

> Listed for the model year, not checked against your VIN. Acura confirms which apply.
> Check your VIN with Acura Canada or call a Acura dealer with your VIN.
> www.acura.ca/en/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,495[5], $1,493 under the median of $27,988[4].



Lowest ask	$24,495
Middle half	$26,120 – $29,499
Median ask	$27,988
This car	$26,495

Same configuration · 8 live listings · as of 27 Oct 2026

OTHER 2019 ACURA MDX LISTINGS [5]

Vernon, BC · 167,597 km	$28,995
Halifax, NS · 133,405 km	$29,800
Airdrie, AB · 138,933 km	$30,531
Thunder Bay, ON · 59,719 km	$36,000
Olds, AB · 138,933 km	$30,531
Hope, BC · 133,794 km	$30,290

§4 EVENTS

2019	Model year 2019[1] Assembly plant East Liberty, Ohio, United States
1 Nov 2018	Transport Canada recall 2018602[2] Issued for the model year · Brakes
28 Mar 2019	Transport Canada recall 2019159[2] Issued for the model year · Lights and instruments
11 Apr 2019	Transport Canada recall 2019179[2] Issued for the model year · Engine
26 Mar 2021	Transport Canada recall 2021182[2] Issued for the model year · Fuel system
8 Nov 2023	Transport Canada recall 2023603[2] Issued for the model year · Engine
18 Dec 2023	Transport Canada recall 2023679[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262[2] Issued for the model year · Fuel system
17 Apr 2025	Transport Canada recall 2025212[2] Issued for the model year · Lights and instruments
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
4 Jun 2026	Transport Canada recall 2026275[2] Issued for the model year · Structure
19 Oct 2026	Listed for sale, Hamilton, ON[5] KNA Motors Inc · asking $26,495
27 Oct 2026	Listing last updated[5] asking $26,495

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.