Register entry, as of 26 October 2026 Listed for sale Record ID 9f457562a9af

2026 Lincoln Aviator Reserve

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

5LM	5J7XC	7	T	G	L18505
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lincoln · FORD MOTOR CO…	Aviator · 3.0 L	Verified	2026	Chicago	Build sequence

§1 IDENTITY [1]

Model year	2026	Engine	3.0 L, 6 cylinders
Make	Lincoln	Fuel	Gasoline
Model	Aviator	Drive	AWD
Trim	Reserve	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Chicago, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/aviator/2026

4 recalls listed by Transport Canada for this model year

Seats and restraints

2026340 14 Jul 2026

Issue: On certain vehicles, the driver's seat could recline on its own when using certain remote features including remote door unlocking, remote start and/or approaching the vehicle with the key fob. As a result, the second-row passenger could become trapped between the seat and the seatback. Note: This recall only affects certain vehicles equipped with memory seats. Safety Risk: A seat that reclines on its own could increase the risk of injury and/or entrapment. Corrective actions: Ford will notify owners by mail. The corrective actions for this recall are under development.

Seats and restraints

2026339 14 Jul 2026

Issue: On certain vehicles the recall repairs completed by a Ford dealer during recall 25S67 (Transport Canada recall no. 2025-328) may not be effective. As a result, a second repair is required. On certain vehicles, the trim for the seat fold switch on the second-row outboard seats could become stuck. If this happens, the seat(s) could fold and/or move unexpectedly. Note: This recall replaces Transport Canada recall no. 2025-328. Vehicles that were repaired under that recall also require this repair. Safety Risk: A seat that folds and/or moves could increase the risk of injury in a crash. Corrective Action: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the seat fold switch trim and housing for one with an improved design.

Heater and defroster

2026159 1 Apr 2026

Issue: On a small number of vehicles, the ground connection for the heating, ventilation and air conditioning (HVAC) blower motor may not have been secured properly. As a result, the defroster could stop working, and you may not be able to defog or defrost the windshield. Safety Risk: A windshield defroster/defogger that doesn't work could cause reduced visibility and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, secure the ground connection(s) in the instrument panel.

Seats and restraints

2026124 17 Mar 2026

Issue: On certain vehicles, the second-row outboard seat belt anchor bolt(s) may be loose or missing. As a result, the seat belt(s) could detach in a crash. Safety Risk: A seat belt that detaches could increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, install, tighten or replace seat belt anchor bolt(s).

> Listed for the model year, not checked against your VIN. Lincoln confirms which apply.
> Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.
> www.lincolncanada.com/support/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $884,949[5], $790,917 over the median of $94,032[4].

Lowest ask	$67,999
Middle half	$88,559 – $97,045
Median ask	$94,032
This car	$884,949

Same configuration · 60 live listings · as of 26 Oct 2026

OTHER 2026 LINCOLN AVIATOR LISTINGS [5]

Unity, SK · 16,378 km	$84,774
Watford, ON · 8,396 km	$88,334
Windsor, ON · 3,145 km	$83,745
Windsor, ON · 5 km	$861,449
Windsor, ON · 986 km	$88,870
Windsor, ON · 5 km	$852,449

§4 EVENTS

2026	Model year 2026[1] Assembly plant Chicago, Illinois, United States
17 Mar 2026	Transport Canada recall 2026124[2] Issued for the model year · Seats and restraints
1 Apr 2026	Transport Canada recall 2026159[2] Issued for the model year · Heater and defroster
14 Jul 2026	Transport Canada recall 2026340[2] Issued for the model year · Seats and restraints
14 Jul 2026	Transport Canada recall 2026339[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Toronto, ON[5] Midtown Honda · asking $884,949

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 60 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.